PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	er Inf	orm	ation											
# of Crash # Not preventat Crash Details (Crashes listed represent Date DOT # Inspection Summary				Firs	st Name		License #					State								
VELASCO				MA	RCOS ANTONIO		D41	09859	9				CA							
VELASCO				MA	RCOS		D41	09859	9				CA							
ANTONIOV	ELASCC)		MA	RCOS ANTONIO		D41	09859	9			CA								
ANTONIO				MA	RCOS ANTONIO		D41	09859	9	СА										
	Crash Activity																			
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
		ł	# of Crashes:	0		# of Crashes with Fata	alities:	0			# of Cras	nes with Ir	CA co responsibility.) s with Injuries: 0 # of Tow # of Injuries: 0 # of Hazmat Re responsibility.) Rpt St Report Number Location # Fatalities				waways:	0		
		# Not	preventable:	0		# of Fata	alities:	0				# of Ir	njuries:	0			# of Hazmat R	of Hazmat Releases: 0		
Crash Det	tails (C	rashes listed r	epresent a c	lrive	r's involvement	in FMCSA-reportable cr	rashes	, wit	hout any o	eterm	ination as t	o respon	sibility	·.)						
D	ate	DOT #	Car	rier N	ame	Driver Name	Driver Lic			State	Driver DOB	Rpt St	Rpt St Report Number			ocation	# Fatalities	# Injur	ies	
					Inspe	ction Activity (3 year	r histo	ory f	rom MCN	IIS sn	apshot da	te)								
Inspection	n Sumn	nary																		
Driver Summary					Vehicle Summary					Hazmat Summary										
Driver Inspections: 6					Vehicle Inspections: 4 Hazma					lazmat Ins	mat Inspections						0			
Driver Out-	-of-servi	ce Inspections:			0	Vehicle Out-of-service Ins	spectio	ns:			1	lazmat Ou	it-of-ser	vice Ir	spection	ons:			0	
Driver Out-of-service Rate: 0					0%	Vehicle Out-of-service Rate:					25% H	Hazmat Out-of-service Rate: 0						0%		

Report executed at: 2/9/2022 3:56:32 PM

MCMIS snapshot date: 01/28/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspe	ction Details													
Carrie	r Info				Driver Info				Inspect	tion Info				
	Date	DOT #	Carrier Name		Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	05/28/2019	3157266	SNAPEEE CORF	>	VELASCO, MARCOS	D4109859	CA	12/19/1978	CO	PF10204165	N	3	0	
2	03/10/2020	3134501	HYUNDAI GLOBA EXPRESS USA IN		VELASCO, MARCOS	D4109859	CA	12/24/1978	CA	UFV3000597	N	2	1	
	Vehicle \	/iolation:	392.2RG	State	vehicle registration or License Plate violatio	n	NON-C	DOS						
3	03/22/2020	3134501	HYUNDAI GLOBA EXPRESS USA IN		VELASCO, MARCOS	D4109859	CA	12/24/1978	CA	ND00001033	N	2	1	
	Driver Vi	olation:	395.34(a)(1)	Failing	to note malfunction that requires use of pa	iper log	NON-C	DOS						
4	04/13/2020	3134501	HYUNDAI GLOBA EXPRESS USA IN		VELASCO, MARCOS	D4109859	CA	12/24/1978	ТХ	5PS50XLS3W	N	2	6	
	Vehicle \	/iolation:	393.9(a)	Inoper	able Required Lamp		NON-C	DOS			•			
	Vehicle Violation:		393.13(c)(2)		Lower Rear retroreflective sheeting or reflex reflective material equired for vehicles manufactured before December 1993			NON-OOS						
	Vehicle \	/iolation:	393.11	Truck- reflecti 1997	uck-Tractor lower rear mud flaps retroreflective sheeting / reflex lective material requirements for vehicles manufactured after July 97			NON-OOS						
	Driver Vi	olation:	395.22(h)(1)	Driver failing to maintain ELD user's manual Driver failing to maintain ELD instruction sheet			NON-OOS NON-OOS							
	Driver Vi	olation:	395.22(h)(2)											
	Driver Vi	olation:	395.22(h)(3)		failed to maintain instruction sheet for ELD ng requirements	malfunction	NON-C	DOS						
5	05/23/2020	3134501	HYUNDAI GLOBA EXPRESS USA IN		VELASCO, MARCOS	D4109859	CA	12/24/1978	CA	ND7U002053	N	1	6	
	Vehicle \	/iolation:	396.3(a)(1)	equal	ES OUT OF SERVICE: The number of defe to or greater than 20 percent of the service e or combination		C	DOS						
	Vehicle Violation:		393.47(e)	Clamp	or Roto type brake out-of-adjustment		NON-OOS							
Vehicle Violation:		/iolation:	393.53(b)	CMV manufactured after 10/19/94 has an autom adjustment system that fails to compensate for w			NON-OOS							
	Vehicle \	/iolation:	393.47(e)	Clamp	or Roto type brake out-of-adjustment		NON-OOS							
	Vehicle \	/iolation:	392.2	Violati	Violation of Local Laws - Explain:			NON-OOS						
	Vehicle \	/iolation:	393.207(f)	Air sus	spension pressure loss		NON-OOS							

Report executed at: 2/9/2022 3:56:32 PM

MCMIS snapshot date: 01/28/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

6	12/07/2021	3134501	HYUNDAI GLOBAL EXPRESS USA INC	VELASCO, MARCOS	D4109859	CA	12/24/1978	MS	U029004605	N	3	0	
Violati	on Summary	/											
Vi	iolation #		Description								# of Out-of-service Violations		
392.2R0	G	State vehicle r	egistration or License Plate vi	olation						1		0	
396.3(a))(1)	BRAKES OUT combination	OF SERVICE: The number of	f defective brakes is equal to or grea	ter than 20 percent of the serv	ice brakes	on the vehicle of	or		1		1	
393.47(e)	Clamp or Roto type brake out-of-adjustment								2		: 0	
393.53(l	b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								1		0	
392.2		Violation of Lo	cal Laws - Explain:							1		0	
393.207	7(f)	Air suspension pressure loss							1		0		
393.9(a))	Inoperable Re	quired Lamp							1		0	
393.13(c)(2)	No Lower Rea	r retroreflective sheeting or re	flex reflective material as required fo	r vehicles manufactured before	Decembe	er 1993			1		0	
393.11		Truck-Tractor	lower rear mud flaps retrorefle	ctive sheeting / reflex reflective mate	erial requirements for vehicles	nanufactu	red after July 19	97		1		0	
395.22(I	h)(1)	Driver failing to	o maintain ELD user's manual							1		0	
395.22(I	h)(2)	Driver failing to maintain ELD instruction sheet 1									0		
395.22(I	h)(3)	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements 1									0		
395.34(a	a)(1)	Failing to note	malfunction that requires use	of paper log						1		0	

The summary counts and rates only include violations that were attributable to VELASCO, MARCOS ANTONIO.

Report executed at: 2/9/2022 3:56:32 PM

MCMIS snapshot date: 01/28/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.