

PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | | | |
|--|------|------------|--------------|-------------------------------------|------------|-------|------------|------------------------------------|---------------|----------|--------------|-----------------------|--|---|--|
| Last Name | | First Name | | License # | | | State | | | | | | | | |
| WHITE | | DWIGHT | | 09737462 | | | TX | | | | | | | | |
| Crash Activity | | | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| # of Crashes: | | 0 | | # of Crashes with Fatalities: | | 0 | | # of Crashes with Injuries: | | 0 | | # of Towaways: | | 0 | |
| # Not preventable: | | 0 | | # of Fatalities: | | 0 | | # of Injuries: | | 0 | | # of Hazmat Releases: | | 0 | |
| Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Location | # Fatalities | # of Injuries | | | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | | | |
| Driver Summary | | | | Vehicle Summary | | | | Hazmat Summary | | | | | | | |
| Driver Inspections: | | 3 | | Vehicle Inspections: | | 2 | | Hazmat Inspections | | | | 0 | | | |
| Driver Out-of-service Inspections: | | 0 | | Vehicle Out-of-service Inspections: | | 2 | | Hazmat Out-of-service Inspections: | | | | 0 | | | |
| Driver Out-of-service Rate: | | 0% | | Vehicle Out-of-service Rate: | | 100% | | Hazmat Out-of-service Rate: | | | | 0% | | | |

Report executed at: 2/24/2024 6:11:19 PM

MCMIS snapshot date: 01/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| Inspection Details | | | | | | | | | | | | |
|--|---|---------|------------------------------------|---------------|------------|-------|------------|-----------------|-----------------|--------------------------------|------------|-----------|
| Carrier Info | | | | Driver Info | | | | Inspection Info | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol |
| 1 | 03/10/2022 | 3451900 | BEELINE EXPRESS TRANSPORTATION INC | WHITE, DWIGHT | 09737462 | TX | 07/11/1970 | CA | UEKX001609 | N | 1 | 3 |
| Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS Vehicle Violation: 393.47(d) All Brakes - Insufficient brake lining thickness OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories NON-OOS | | | | | | | | | | | | |
| 2 | 10/07/2022 | 213754 | USA TRUCK LLC | WHITE, DWIGHT | 09737462 | TX | 07/11/1970 | AR | 568E005437 | N | 3 | 0 |
| 3 | 03/01/2023 | 312894 | UNLIMITED TRUCKING INC | WHITE, DWIGHT | 09737462 | TX | 07/11/1970 | TX | 6J0F0XCVT7 | N | 2 | 4 |
| Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperative Brake Lamps OOS | | | | | | | | | | | | |
| Violation Summary | | | | | | | | | | | | |
| Violation # | Description | | | | | | | | # of Violations | # of Out-of-service Violations | | |
| 393.9(a) | Inoperable Required Lamp | | | | | | | | 3 | 1 | | |
| 393.11 | Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 | | | | | | | | 1 | 0 | | |
| 396.3(a)(1) | BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination | | | | | | | | 2 | 1 | | |
| 393.47(d) | All Brakes - Insufficient brake lining thickness | | | | | | | | 1 | 1 | | |

The summary counts and rates only include violations that were attributable to WHITE, DWIGHT.

Report executed at: 2/24/2024 6:11:19 PM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>