

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
BAYYAC		ABDIKADIR		C543093637012			MN								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	04/06/2019	241572	LANDSTAR RANGER INC	BAYYAC, ABDIKADIR	C543093637012	MN	01/10/1982	NC	0006078277	N	3	0			
2	03/10/2020	2467439	KANIA INC	BAYYAC, ABDIKADIR	C543093637012	MN	01/10/1982	WI	2734000658	N	2	1			
Driver Violation:		392.2C		Failure to obey traffic control device				NON-OOS							

Report executed at: 4/7/2022 6:16:22 PM

MCMIS snapshot date: 03/25/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

3	06/29/2020	2467439	KANIA INC	BAYYAC, ABDIKADIR	C543093637012	MN	01/10/1982	IA	000P10FVFR	N	3	0
4	09/13/2021	2400940	YUSUF MOHAMED DAGANE	BAYYAC, ABDIKADIR	C543093637012	MN	01/10/1982	MN	0ADS000801	N	2	3
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperative Brake Lamps			OOS						
Vehicle Violation:		393.11	No or defective lighting devices or reflective material as required			NON-OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998							1			
393.9(a)		Inoperative Brake Lamps							1			
393.11		No or defective lighting devices or reflective material as required							1			
392.2C		Failure to obey traffic control device							1			

The summary counts and rates only include violations that were attributable to BAYYAC, ABDIKADIR.

Report executed at: 4/7/2022 6:16:22 PM

MCMIS snapshot date: 03/25/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.