

PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | | | |
|--|------------|------------|----------------------|-------------------------------------|------------|-------|------------|------------------------------------|-----------------|-------------|--------------|-----------------------|--|---|--|
| Last Name | | First Name | | License # | | | State | | | | | | | | |
| RENDON | | MARIO | | 35117059 | | | TX | | | | | | | | |
| Crash Activity | | | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| # of Crashes: | | 0 | | # of Crashes with Fatalities: | | 0 | | # of Crashes with Injuries: | | 0 | | # of Towaways: | | 0 | |
| # Not preventable: | | 0 | | # of Fatalities: | | 0 | | # of Injuries: | | 0 | | # of Hazmat Releases: | | 0 | |
| Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Location | # Fatalities | # of Injuries | | | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | | | |
| Driver Summary | | | | Vehicle Summary | | | | Hazmat Summary | | | | | | | |
| Driver Inspections: | | 4 | | Vehicle Inspections: | | 3 | | Hazmat Inspections | | | | 0 | | | |
| Driver Out-of-service Inspections: | | 0 | | Vehicle Out-of-service Inspections: | | 1 | | Hazmat Out-of-service Inspections: | | | | 0 | | | |
| Driver Out-of-service Rate: | | 0% | | Vehicle Out-of-service Rate: | | 33% | | Hazmat Out-of-service Rate: | | | | 0% | | | |
| Inspection Details | | | | | | | | | | | | | | | |
| Carrier Info | | | | Driver Info | | | | | Inspection Info | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol | | | |
| 1 | 09/09/2020 | 1970020 | UNIMEX LOGISTICS LLC | RENDON, MARIO | 35117059 | TX | 01/10/1995 | IL | 4069410039 | N | 3 | 0 | | | |

Report executed at: 5/11/2023 11:55:03 AM

MCMIS snapshot date: 04/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| | | | | | | | | | | | | |
|--------------------|------------|--------------|---|---------------|----------|----|------------|----|------------|---|---|---|
| 2 | 11/14/2020 | 1970020 | UNIMEX LOGISTICS LLC | RENDON, MARIO | 35117059 | TX | 01/10/1995 | TX | 5VRC0XVKF0 | N | 2 | 5 |
| Vehicle Violation: | | 393.75(a)(3) | Tire-flat and/or audible air leak | | OOS | | | | | | | |
| Vehicle Violation: | | 393.9(a) | Inoperable Required Lamp | | NON-OOS | | | | | | | |
| Vehicle Violation: | | 393.11 | Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 | | NON-OOS | | | | | | | |
| Vehicle Violation: | | 393.45 | Brake tubing and hose adequacy | | OOS | | | | | | | |
| Vehicle Violation: | | 396.3(a)(1) | Inspection, repair and maintenance of parts & accessories | | NON-OOS | | | | | | | |
| 3 | 07/22/2022 | 1339068 | LOGISTIC ONE LTD | RENDON, MARIO | 35117059 | TX | 01/10/1995 | TX | 6CUA0AKO0W | N | 1 | 3 |
| Vehicle Violation: | | 393.13(c)(3) | No Upper Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993 | | NON-OOS | | | | | | | |
| Vehicle Violation: | | 393.13(c)(2) | No Lower Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993 | | NON-OOS | | | | | | | |
| Vehicle Violation: | | 393.55(e) | No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 | | NON-OOS | | | | | | | |
| 4 | 08/18/2022 | 1339068 | LOGISTIC ONE LTD | RENDON, MARIO | 35117059 | TX | 01/10/1995 | TX | 6DL90ALRGX | N | 2 | 0 |

Violation Summary

| Violation # | Description | # of Violations | # of Out-of-service Violations |
|--------------|---|-----------------|--------------------------------|
| 393.13(c)(3) | No Upper Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993 | 1 | 0 |
| 393.13(c)(2) | No Lower Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993 | 1 | 0 |
| 393.55(e) | No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 | 1 | 0 |
| 393.75(a)(3) | Tire-flat and/or audible air leak | 1 | 1 |
| 393.9(a) | Inoperable Required Lamp | 1 | 0 |
| 393.11 | Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 | 1 | 0 |
| 393.45 | Brake tubing and hose adequacy | 1 | 1 |
| 396.3(a)(1) | Inspection, repair and maintenance of parts & accessories | 1 | 0 |

The summary counts and rates only include violations that were attributable to RENDON, MARIO.

Report executed at: 5/11/2023 11:55:03 AM

MCMIS snapshot date: 04/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>