PSP Detailed Report

Federal Motor Carrier Safety Administration

No crash or inspection results found.

Driver Information																				
Last Name First					First Name				License #						State					
MORENO					JOSE ELISEO				E2149538						CA					
MORENOGOMEZ					JOSE ELISEO				E2149538						СА					
GOMEZMORENO					JOSE ELISEO				E2149538						CA					
GOMEZ					JOSE ELISEO				E2149538						CA					
	Crash Activity																			
Cras	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
# of Crashes:					0 # of Crashes with Fataliti				s: 0				# of Cras	shes with I	njuries	s: 0	# of To			vaways: ₀
# Not preventable:					0 # of Fatalit				s: 0					# of I	Injuries: 0 # of Hazmat I				# of Hazmat Ro	eleases: 0
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
Date DOT # Carrie			ier N	ame		Driver Name		Driver Lic			State	e Driver DOB Rpt S		t Report Number		nber	Location	# Fatalities	# Injuries	
					Inspection Activity (3 year h					nistory from MCMIS snapshot date)										
Insp	Inspection Summary																			
Driver Summary Vel								Vehic	hicle Summary						Hazmat Summary					
Driver Inspections:						0	0 Vehicle Inspections:						0	Hazmat Inspections					0	
Driver Out-of-service Inspections:						0	0 Vehicle Out-of-service Inspections: 0 Haz					Hazmat O	azmat Out-of-service Inspections: 0							
Driver Out-of-service Rate:						0%	0% Vehicle Out-of-service Rate:					0%	Hazmat Out-of-service Rate: 0%							
Insp	Inspection Details																			
Carrier Info					C	Driver Info							Inspection Info							

Report executed at: 8/19/2021 9:07:23 AM

MCMIS snapshot date: 07/30/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
Violation Summary												
Vi	Violation # Description									ons	# of Out-of-service Violations	

The summary counts and rates only include violations that were attributable to MORENO, JOSE ELISEO.

Report executed at: 8/19/2021 9:07:23 AM MCMIS snapshot date: 07/30/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.