

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name			License #			State						
RABILERO	ERNESTO JAVIER			C234210803890			FL						
CASTILLORABILERO	ERNESTO			C234210803890			FL						
CASTILLO	ERNESTO JAVIER			C234210803890			FL						
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		1	Vehicle Inspections:		0	Hazmat Inspections		0					
Driver Out-of-service Inspections:		0	Vehicle Out-of-service Inspections:		0	Hazmat Out-of-service Inspections:		0					
Driver Out-of-service Rate:		0%	Vehicle Out-of-service Rate:		0%	Hazmat Out-of-service Rate:		0%					

Report executed at: 2/26/2024 12:22:47 PM

MCMIS snapshot date: 01/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	02/10/2022	3762402	OLAYON SERVICES INC	CASTILLO RABILERO, ERNESTO	C234210803890	FL	10/29/1980	MS	U038007451	N	3	0
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	

The summary counts and rates only include violations that were attributable to RABILERO, ERNESTO JAVIER.

Report executed at: 2/26/2024 12:22:47 PM

MCMIS snapshot date: 01/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.