PSP Detailed Report

Federal Motor Carrier Safety Administration

							Driv	er Inf	for	matio	n										
Last Name First Name				st Name L			Lice	License #						State							
YERABANDOMO R				RA	RANGEL				Y615720624660						FL						
	Crash Activity																				
Cras	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																				
# of Crashes: 0						# of Crashes with Fata	alities:	ties: 0			# of Crash	njuries:	0	# of Tow			waways	: 0			
# Not preventable: 0				0	# of Fatalit				0)				# of li	njuries:	0	# of Hazmat Rele			eleases	: 0
Cras	sh Details (C	rashes listed ı	epresent a d	rive	r's involveme	ent i	n FMCSA-reportable cr	rashes	s, w	vithout	any de	etermi	ination as to	respon	sibility	·.)					
	Date DOT # Carrier Name				Driver Name	Driver Lic				State	Driver DOB	DB Rpt St Report Numb			er	er Location # Fatalitie		# of Injuries			
Inspec						ction Activity (3 year	hista	history from MCMIS snapshot d					e)			_					
	Inspection Activity (3 year history from MCMIS snapshot date)																				
Insp	ection Sumi	mary																			
Driver Summary							Vehicle Summary						Hazmat Summary								
Driver Inspections: 4						Vehicle Inspections: 3					3 H	Hazmat Inspections							0		
Driver Out-of-service Inspections: 0						Vehicle Out-of-service Inspections:						2 H	Hazmat Out-of-service Inspections:						0		
Driver Out-of-service Rate: 0					0%	Vehicle Out-of-service Rate:						67% H	Hazmat Out-of-service Rate: 0						0%		

Report executed at: 9/6/2023 9:53:39 AM MCMIS snapshot date: 08/25/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspe	ction Details											
Carrie	r Info			Driver Info	Inspection Info							
	Date	DOT#	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/04/2022	2334923	BLACK & CHROME INC	YERA BANDOMO, RANGEL	RA BANDOMO, RANGEL Y615720624660 FL		12/26/1962	NY	SPB0301380	N	2	5
Driver Violation:		iolation:	392.2 Failui	ure to obey traffic control device			oos				•	
Driver Violation:		iolation:	391.11(b)(2) Drive response	NON-0	NON-OOS							
Vehicle Violation:			393.75(a)(3) Tire-f	oos								
Vehicle Violation:			393.75(a)(3) Tire-f	oos								
	Vehicle \	Violation:	393.55(d)(1) CMV Tract	NON-OOS								
2	05/12/2022	05/12/2022 2334923 BLACK & CHROME INC		YERA, RANGEL Y615720624		FL	12/26/1962 TX		6AV90XRBFM	N	2	0
3	04/18/2023	3243700	BORDERLANDERS INC	YERA BANDOMO, RANGEL	Y615720624660	FL	12/26/1962	NM	0749N30K0F	N	2	1
Vehicle		violation:	393.75(a)(3) Tire-f	lat and/or audible air leak	oos					•	•	
4	06/27/2023	3243700	BORDERLANDERS INC	YERA BANDONO, RANGEL (co-driver)	Y615720624660	FL	12/26/1962	ID	6500000176	N	3	1
Driver V		iolation:	ation: 392.2 Improper turns NON-OOS - This violation does N								O, RANGEL.	
Violat	ion Summary	1										
Violation #		Description							# of Violati	# of Violations		
393.75(a)(3)		Tire-flat and/	or audible air leak		3	3						
392.2		Failure to ob	ey traffic control device		1	0						
391.11(b)(2)		Driver canno	t read or speak the English lange		1		(

CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)

The summary counts and rates only include violations that were attributable to YERABANDOMO, RANGEL.

Report executed at: 9/6/2023 9:53:39 AM MCMIS snapshot date: 08/25/2023

393.55(d)(1)

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.