

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
VAILLANTCUADRA	CUADRA	V453280852510	FL										
VAILLANT	GERMAN	V453280852510	FL										
CUADRA	GERMAN	V453280852510	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		8		Vehicle Inspections:		5		Hazmat Inspections			0		
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:			0		
Driver Out-of-service Rate:		12%		Vehicle Out-of-service Rate:		40%		Hazmat Out-of-service Rate:			0%		
Inspection Details													
Carrier Info				Driver Info				Inspection Info					
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	02/07/2022	3032794	ROAD LIFE TRUCKING CORP	VAILLANT CUADRA, GERMAN	V453280852510	FL	07/11/1985	MD	3270000355	N	1	3	

Report executed at: 9/11/2024 9:47:14 AM

MCMIS snapshot date: 08/30/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS Vehicle Violation: 393.75(a) Flat tire or fabric exposed OOS Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking NON-OOS												
2	06/30/2022	3032794	ROAD LIFE TRUCKING CORP	VAILLANT, GERMAN	V453280852510	FL	07/11/1985	TX	6C890XDB3S	N	2	3
Vehicle Violation: 393.9(a) Inoperative turn signal OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Driver Violation: 383.23(a)(2) Operating a CMV without a CDL OOS												
3	10/17/2022	3032794	ROAD LIFE TRUCKING CORP	VAILLANT CUADRA, GERMAN (co-driver)	V453280852510	FL	07/11/1985	AZ	0223011611	N	2	7
Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts and accessories NON-OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Vehicle Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001 NON-OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Driver Violation: 395.24(c)(2)(ii) Driver failed to manually add the trailer number NON-OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Driver Violation: 391.15(a) Driving a CMV while disqualified. Suspended for safety-related or unknown reason and in the state of drivers license issuance. OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN. Driver Violation: 390.3(e) Driver prohibited from performing safety sensitive functions per 382.501(a) in the Drug and Alcohol Clearinghouse. OOS - This violation does NOT apply to VAILLANT CUADRA, GERMAN.												
4	10/20/2022	3032794	ROAD LIFE TRUCKING CORP	VAILLANT CUADRA, GERMAN	V453280852510	FL	07/11/1985	LA	LAIW006487	N	1	4
Driver Violation: 395.30(b)(1) Driver failed to certify the accuracy of the information gathered by the ELD NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS												
5	07/19/2023	3492085	OPTIMUS PRIME FREIGHT LLC	VAILLANT, CUADRA	V453280852510	FL	07/11/1985	IA	000P13RHXC	N	3	1
Driver Violation: 395.8(e)(1) False Record of Duty Status - Improper use of Personal Conveyance Exception NON-OOS												
6	10/03/2023	1213613	ROLAND TRANSPORT INC	VAILLANT, GERMAN	V453280852510	FL	07/11/1985	NE	T241000001	N	3	0
7	10/27/2023	1213613	ROLAND TRANSPORT INC	VAILLANT CUADRA, GERMAN	V453280852510	FL	07/11/1985	UT	24IC000036	N	3	0
8	06/19/2024	3319729	DM CARRIER CORP	VAILLANT CUADRA, GERMAN	V453280852510	FL	07/11/1985	FL	4895000216	N	2	0

Report executed at: 9/11/2024 9:47:14 AM

MCMIS snapshot date: 08/30/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
395.8(e)(1)	False Record of Duty Status - Improper use of Personal Conveyance Exception	1	0
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	1	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.95(a)	No/discharged/unsecured fire extinguisher	1	0
393.75(a)	Flat tire or fabric exposed	1	1
393.45(b)(2)	Brake hose or tubing chafing and/or kinking	1	0
393.9(a)	Inoperative turn signal	2	1
383.23(a)(2)	Operating a CMV without a CDL	1	1

The summary counts and rates only include violations that were attributable to VAILLANTCUADRA, CUADRA.

Report executed at: 9/11/2024 9:47:14 AM

MCMIS snapshot date: 08/30/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.