

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MOLINABRICENO	YEISSON JOSE	B73897897104902	NJ										
MOLINA	YEISSON JOSE	B73897897104902	NJ										
JOSEMOLINA	YEISSON JOSE	B73897897104902	NJ										
JOSEBRICENOMOLINA	YEISSON JOSE	B73897897104902	NJ										
JOSEBRICENO	YEISSON JOSE	B73897897104902	NJ										
JOSE	YEISSON JOSE	B73897897104902	NJ										
BRICENOMOLINAJOSE	YEISSON JOSE	B73897897104902	NJ										
BRICENOMOLINA	YEISSON	B73897897104902	NJ										
BRICENOMOLINA	YEISSON JOSE	B73897897104902	NJ										
BRICENOJOSE	YEISSON JOSE	B73897897104902	NJ										
BRICENO	YEISSON JOSE	B73897897104902	NJ										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					

Report executed at: 5/23/2023 3:20:21 PM

MCMIS snapshot date: 04/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Driver Inspections:	2	Vehicle Inspections:	1	Hazmat Inspections	0
Driver Out-of-service Inspections:	0	Vehicle Out-of-service Inspections:	0	Hazmat Out-of-service Inspections:	0
Driver Out-of-service Rate:	0%	Vehicle Out-of-service Rate:	0%	Hazmat Out-of-service Rate:	0%

Inspection Details

Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	01/13/2021	2350561	VS INSTALLATION INC	BRICENO-MOLINA, YEISSON	B73897897104902	NJ	04/12/1990	NJ	SPPUI00269	N	1	1
Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS												
2	09/29/2022	3082095	AMERICAN CARGO ENTERPRISE LLC	BRICENO MOLINA, YEISSON	B73897897104902	NJ	04/12/1990	NY	SPWD090737	N	3	1
Vehicle Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS												

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State or International Fuel Tax (IFTA) Violation	1	0
393.9(a)	Inoperative turn signal	1	0

The summary counts and rates only include violations that were attributable to MOLINABRICENO, YEISSON JOSE.

Report executed at: 5/23/2023 3:20:21 PM

MCMIS snapshot date: 04/28/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>