

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
VEGA	JOSE ANTONIO	G521421683740	FL										
GOMEZVEGA	JOSE	G521421683740	FL										
GOMEZ	JOSE ANTONIO	G521421683740	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		33%		Hazmat Out-of-service Rate:				0%	

Report executed at: 5/15/2024 3:12:59 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/16/2021	2089174	AREL TRUCKING INC	GOMEZ VEGA, JOSE	G521421683740	FL	10/14/1968	MT	L248002955	N	1	2
Vehicle Violation: 393.40 Inadequate brake system on a CMV NON-OOS												
Vehicle Violation: 396.3(a)(1) Brake system pressure loss OOS												
2	09/17/2021	2089174	AREL TRUCKING INC	GOMEZ, JOSE	G521421683740	FL	10/14/1968	TN	BBAA033451	N	2	1
Vehicle Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups. NON-OOS												
3	04/25/2023	1284430	NORTH AMERICAN TRANSPORT SERVICES LLC	GOMEZ VEGA, JOSE	G521421683740	FL	10/14/1968	PA	F602311514	N	2	2
Vehicle Violation: 393.45(d) Brake Connections with Leaks Under Vehicle NON-OOS												
Vehicle Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001 NON-OOS												
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.45(d)		Brake Connections with Leaks Under Vehicle							1		0	
393.55(d)(3)		No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001							1		0	
393.40		Inadequate brake system on a CMV							1		0	
396.3(a)(1)		Brake system pressure loss							1		1	
392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.							1		0	

The summary counts and rates only include violations that were attributable to VEGA, JOSE ANTONIO.

Report executed at: 5/15/2024 3:12:59 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>