

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
LAURADIN	JOSUE	L635420823750	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		5		Vehicle Inspections:		4		Hazmat Inspections			0		
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:			0		
Driver Out-of-service Rate:		20%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:			0%		
Inspection Details													
Carrier Info				Driver Info					Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	10/25/2021	3633900	SUPER GREEN LOGISTICS LLC	LAURADIN, JOSUE	L635420823750	FL	10/15/1982	FL	3198011884	N	3	1	
Driver Violation:		392.2		Lane Restriction violation		NON-OOS							

Report executed at: 6/9/2023 2:23:41 PM

MCMIS snapshot date: 05/26/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	02/17/2022	3745684	ONETAZO TRUCK LLC	LAURADIN, JOSUE	L635420823750	FL	10/15/1982	WV	4736000901	N	2	0
3	03/02/2022	3745684	ONETAZO TRUCK LLC	LAURADIN, JOSUE	L635420823750	FL	10/15/1982	SC	R335000432	N	2	11
Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.8(e)(1) False report of drivers record of duty status NON-OOS Driver Violation: 395.3(a)(2) Driving beyond 14 hour duty period (Property carrying vehicle) OOS Vehicle Violation: 393.95(f) No / insufficient warning devices NON-OOS												
4	05/11/2022	3793044	EXCELSIOR TRUCKING LOGISTICS LLC	LAURADIN, JOSUE	L635420823750	FL	10/15/1982	SD	004A025959	N	1	9
Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS Vehicle Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment NON-OOS Vehicle Violation: 393.205(c) Wheel fasteners loose and/or missing NON-OOS Vehicle Violation: 393.47(d) All Brakes - Insufficient brake lining thickness NON-OOS Vehicle Violation: 393.47(d) All Brakes - Insufficient brake lining thickness NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal OOS Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS												
5	05/24/2022	3793044	EXCELSIOR TRUCKING LOGISTICS LLC	LAURADIN, JOSUE	L635420823750	FL	10/15/1982	MD	3269000429	N	1	3
Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit OOS Vehicle Violation: 393.47(d) All Brakes - Insufficient brake lining thickness NON-OOS Vehicle Violation: 390.21T(b) Carrier name and/or USDOT Number not displayed as required NON-OOS												

Report executed at: 6/9/2023 2:23:41 PM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Violation Summary			
Violation #	Description	# of Violations	# of Out-of-service Violations
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	1
393.47(d)	All Brakes - Insufficient brake lining thickness	3	0
390.21T(b)	Carrier name and/or USDOT Number not displayed as required	1	0
396.17(c)	Operating a CMV without proof of a periodic inspection	1	0
393.47(e)	Clamp or Roto type brake out-of-adjustment	2	0
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
393.205(c)	Wheel fasteners loose and/or missing	1	0
393.9(a)	Inoperative turn signal	1	1
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	1	1
395.8(e)(1)	False report of drivers record of duty status	9	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle)	1	1
393.95(f)	No / insufficient warning devices	1	0
392.2	Lane Restriction violation	1	0

The summary counts and rates only include violations that were attributable to LAURADIN, JOSUE.

Report executed at: 6/9/2023 2:23:41 PM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>