

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
HUGOCORONA	HECTOR HUGO	B9153306	CA										
HUGOCAZARESCORONA	HECTOR HUGO	B9153306	CA										
HUGOCAZARES	HECTOR HUGO	B9153306	CA										
HUGO	HECTOR HUGO	B9153306	CA										
CORONAHUGO	HECTOR HUGO	B9153306	CA										
CORONACAZARES	HECTOR HUGO	B9153306	CA										
CORONA	HECTOR HUGO	B9153306	CA										
CAZARESHUGO	HECTOR HUGO	B9153306	CA										
CAZARESCORONAHUGO	HECTOR HUGO	B9153306	CA										
CAZARESCORONA	HECTOR	B9153306	CA										
CAZARES	HECTOR HUGO	B9153306	CA										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					

Report executed at: 8/24/2022 2:17:24 PM

MCMIS snapshot date: 07/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Driver Inspections:	14	Vehicle Inspections:	11	Hazmat Inspections	0
Driver Out-of-service Inspections:	0	Vehicle Out-of-service Inspections:	2	Hazmat Out-of-service Inspections:	0
Driver Out-of-service Rate:	0%	Vehicle Out-of-service Rate:	18%	Hazmat Out-of-service Rate:	0%

Inspection Details

Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/29/2021	3463899	CESAR ANTONIO ALZATE	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UEHJ002000	N	3	0
2	06/01/2021	3463899	CESAR ANTONIO ALZATE	CAZARES CORONA, HECTOR	B9153306	CA	09/23/1982	CA	NDHX002897	N	2	2
Vehicle Violation: 393.9(a)				Inoperative turn signal				OOS				
Vehicle Violation: 393.9(a)				Inoperative turn signal				OOS				
3	06/04/2021	3463899	CESAR ANTONIO ALZATE	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	NDLU002921	N	1	1
Vehicle Violation: 396.3(a)(1)				Brakes (general) Explain:				NON-OOS				
4	07/08/2021	3463899	CESAR ANTONIO ALZATE	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	IL	4127580054	N	3	0
5	08/22/2021	3463899	CESAR ANTONIO ALZATE	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	AZ	0272002958	N	3	3
Driver Violation: 392.2				State/Local Laws - Speeding 15 or more miles per hour over the speed limit.				NON-OOS				
Driver Violation: 395.3(a)(2)				Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation				NON-OOS				
Driver Violation: 395.3(a)(3)(i)				Driving beyond 11 hour driving limit in a 14 hour period. (Property carrying vehicle) - Nominal Violation				NON-OOS				
6	12/09/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001018	N	1	1
Vehicle Violation: 396.3(a)(1)				Brakes (general) Explain:				NON-OOS				
7	12/09/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001019	N	1	0
8	12/09/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001017	N	1	0
9	12/13/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001028	N	1	1
Vehicle Violation: 396.3(a)(1)				Brakes (general) Explain:				NON-OOS				

Report executed at: 8/24/2022 2:17:24 PM

MCMIS snapshot date: 07/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

10	12/13/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001029	N	1	0
11	12/13/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001027	N	1	0
12	12/13/2021	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	CA	UDR3001030	N	1	0
13	02/24/2022	2536137	TO LOGISTICS INC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	AZ	0Y5J000044	N	2	3
Driver Violation: 395.3(a)(3)(i) Driving beyond 11 hour driving limit. (Property Carrying Vehicle) NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
14	05/13/2022	3402954	M LOPEZ TRANSPORT LLC	CAZARESCORONA, HECTOR	B9153306	CA	09/23/1982	NM	2917M3PRFH	N	2	1
Vehicle Violation: 393.9(a) Inoperable head lamps NON-OOS												

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State/Local Laws - Speeding 15 or more miles per hour over the speed limit.	1	0
395.3(a)(2)	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation	1	0
395.3(a)(3)(i)	Driving beyond 11 hour driving limit in a 14 hour period. (Property carrying vehicle) - Nominal Violation	2	0
396.3(a)(1)	Brakes (general) Explain:	3	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.75(a)(3)	Tire-flat and/or audible air leak	1	1
393.9(a)	Inoperable head lamps	3	2

The summary counts and rates only include violations that were attributable to HUGOCORONA, HECTOR HUGO.

Report executed at: 8/24/2022 2:17:24 PM

MCMIS snapshot date: 07/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>