

PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | |
|--|------------|-------------------------------|--|--|------------|------------------------------------|------------|-----------------|---------------|-------------|--------------|---------------|--|
| Last Name | First Name | License # | State | | | | | | | | | | |
| ESTRADA | HEMERSON | D1641278 | CA | | | | | | | | | | |
| Crash Activity | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | |
| # of Crashes: | 0 | # of Crashes with Fatalities: | 0 | # of Crashes with Injuries: | 0 | # of Towaways: | 0 | | | | | | |
| # Not preventable: | 0 | # of Fatalities: | 0 | # of Injuries: | 0 | # of Hazmat Releases: | 0 | | | | | | |
| Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Location | # Fatalities | # of Injuries | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | |
| Driver Summary | | | | Vehicle Summary | | | | Hazmat Summary | | | | | |
| Driver Inspections: | | 4 | Vehicle Inspections: | | 3 | Hazmat Inspections | | 0 | | | | | |
| Driver Out-of-service Inspections: | | 0 | Vehicle Out-of-service Inspections: | | 1 | Hazmat Out-of-service Inspections: | | 0 | | | | | |
| Driver Out-of-service Rate: | | 0% | Vehicle Out-of-service Rate: | | 33% | Hazmat Out-of-service Rate: | | 0% | | | | | |
| Inspection Details | | | | | | | | | | | | | |
| Carrier Info | | | | Driver Info | | | | Inspection Info | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol | |
| 1 | 07/08/2019 | 54283 | SWIFT TRANSPORTATION CO OF ARIZONA LLC | ESTRADA, HEMERSON | D1641278 | CA | 02/26/1983 | CA | NCVL000246 | N | 1 | 1 | |
| Vehicle Violation: | | 393.47(e) | | Clamp or Roto type brake out-of-adjustment | | NON-OOS | | | | | | | |

Report executed at: 7/16/2022 7:49:52 PM

MCMIS snapshot date: 06/24/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| | | | | | | | | | | | | |
|---|------------|---------|--------------------------------|-------------------|----------|----|------------|----|------------|---|---|---|
| 2 | 07/28/2020 | 3399279 | ESTRADA VELASQUEZ TRUCKING LLC | ESTRADA, HEMERSON | D1641278 | CA | 02/26/1983 | AR | 713C000640 | N | 3 | 0 |
| 3 | 09/15/2020 | 3399279 | ESTRADA VELASQUEZ TRUCKING LLC | ESTRADA, HEMERSON | D1641278 | CA | 02/26/1983 | CA | UEKX000701 | N | 2 | 2 |
| Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking OOS | | | | | | | | | | | | |
| 4 | 10/05/2020 | 3399279 | ESTRADA VELASQUEZ TRUCKING LLC | ESTRADA, HEMERSON | D1641278 | CA | 02/26/1983 | CA | NARU002074 | N | 2 | 0 |

Violation Summary

| Violation # | Description | # of Violations | # of Out-of-service Violations |
|--------------|---|-----------------|--------------------------------|
| 393.9(a) | Inoperable Required Lamp | 1 | 0 |
| 393.45(b)(2) | Brake hose or tubing chafing and/or kinking | 1 | 1 |
| 393.47(e) | Clamp or Roto type brake out-of-adjustment | 1 | 0 |

The summary counts and rates only include violations that were attributable to ESTRADA, HEMERSON.

Report executed at: 7/16/2022 7:49:52 PM

MCMIS snapshot date: 06/24/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.