

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
VALENCIA	ULISES	Y3152538	CA										
MARINVALENCIA	ULISES	Y3152538	CA										
MARIN	ULISES	Y3152538	CA										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		7		Vehicle Inspections:		7		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		3		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		43%		Hazmat Out-of-service Rate:				0%	

Report executed at: 5/2/2024 1:48:27 PM

MCMIS snapshot date: 04/04/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/05/2022	2716763	SB INDUSTRIAL VACUUM SERVICES INC	MARIN VALENICA, ULISES	Y3152538	CA	02/01/1972	CA	NABI004152	N	1	2
Vehicle Violation: 393.60(d) Glazing permits < 70% of light NON-OOS Vehicle Violation: 393.9(a) Inoperative Brake Lamps OOS												
2	04/11/2022	2716763	SB INDUSTRIAL VACUUM SERVICES INC	MARINVALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	NDM1003662	N	1	0
3	12/09/2022	2850987	ACTION CLEANUP ENVIRONMENTAL SERVICES INC	MARINVALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	NC4W004190	N	1	2
Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: NON-OOS												
4	04/20/2023	2850987	ACTION CLEANUP ENVIRONMENTAL SERVICES INC	MARIN VALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	NCGL002566	N	1	1
Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS												
5	12/18/2023	2716763	SB INDUSTRIAL VACUUM SERVICES INC	MARINVALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	UEG9000875	N	2	4
Driver Violation: 392.2 Unlawfully parking and/or leaving vehicle in the roadway NON-OOS Driver Violation: 392.2 Violation of Local Laws - Explain: NON-OOS Driver Violation: 392.2 Failure to obey traffic control device NON-OOS Vehicle Violation: 392.2 State vehicle registration or License Plate violation NON-OOS												
6	12/21/2023	2716763	SB INDUSTRIAL VACUUM SERVICES INC	MARINVALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	UFV3003315	N	2	2
Vehicle Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on allowable gross weight. NON-OOS Vehicle Violation: 393.70(b)(2) Kingpin not properly engaged OOS												

Report executed at: 5/2/2024 1:48:27 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

7	02/21/2024	3424229	RODARTE LOGISTICS INC	MARINVALENCIA, ULISES	Y3152538	CA	02/01/1972	CA	NEK3000604	N	1	6
Vehicle Violation:		393.51	No or defective brake warning device or pressure gauge			OOS						
Vehicle Violation:		393.75(a)(3)	Tire-flat and/or audible air leak			OOS						
Vehicle Violation:		390.21T(b)	Carrier name and/or USDOT Number not displayed as required			NON-OOS						
Vehicle Violation:		393.83(g)	Exhaust leak under driver and/or sleeper compartment			NON-OOS						
Vehicle Violation:		393.45(d)	Brake connections with leaks or constrictions			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		State vehicle registration or License Plate violation							7		0	
396.3(a)(1)		Brakes (general) Explain:							1		0	
393.70(b)(2)		Kingpin not properly engaged							1		1	
393.51		No or defective brake warning device or pressure gauge							1		1	
393.75(a)(3)		Tire-flat and/or audible air leak							1		1	
390.21T(b)		Carrier name and/or USDOT Number not displayed as required							1		0	
393.83(g)		Exhaust leak under driver and/or sleeper compartment							1		0	
393.45(d)		Brake connections with leaks or constrictions							1		0	
393.9(a)		Inoperable Required Lamp							2		2	
393.60(d)		Glazing permits < 70% of light							1		0	

The summary counts and rates only include violations that were attributable to VALENCIA, ULISES.

Report executed at: 5/2/2024 1:48:27 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>