

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODRIGUEZ	LAZARO HENRY	G626528703060	FL										
GARCIARODRIGUEZ	LAZARO	G626528703060	FL										
GARCIA	LAZARO HENRY	G626528703060	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 3/26/2024 11:17:50 AM

MCMIS snapshot date: 02/23/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/20/2022	3622445	PAPU & SISTER LLC	GARCIA, LAZARO	G626528703060	FL	08/26/1970	TX	6A980AIMIM	N	2	5
Vehicle Violation:		393.11	No or defective lighting devices or reflective material as required			NON-OOS						
Vehicle Violation:		393.11	No or defective lighting devices or reflective material as required			NON-OOS						
Vehicle Violation:		393.11	Side retroreflective sheeting or reflex reflector requirements for vehicles manufactured after December 1993			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
2	05/15/2022	3622445	PAPU & SISTER LLC	GARCIA RODRIGUEZ, LAZARO	G626528703060	FL	08/26/1970	OR	AAF2006010	N	3	1
Vehicle Violation:		392.9a(a)(1)	Operating without the Required Operating Authority			OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.11		No or defective lighting devices or reflective material as required							3		0	
393.9(a)		Inoperable Required Lamp							2		0	
392.9a(a)(1)		Operating without the Required Operating Authority							1		1	

The summary counts and rates only include violations that were attributable to RODRIGUEZ, LAZARO HENRY.

Report executed at: 3/26/2024 11:17:50 AM

MCMIS snapshot date: 02/23/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>