## **PSP Detailed Report**

## **Federal Motor Carrier Safety Administration**

Driver Information																				
Last Name				First Name				Lic	License #					State						
TOLEDANO				MANUEL ALEJANDRO				P.	R234541864450					FL						
				┖		IDRO														
RUIZ	TOLEDANO			то	LEDANO			R2	234541	864450				FL	-					
RUIZ				MANUEL ALEJANDRO			R2	R234541864450					FL							
		Crash Activity  Inmary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)  # of Crashes: 0 # of Crashes with Fatalities: 0 # of Crashes with Injuries: 0 # of Towaways: 0 # Not preventable: 0 # of Fatalities: 0 # of Fatalities: 0 # of Injuries: 0 # of Hazmat Releases: 0 # of Hazmat Releases: 0 # of Fatalities: 0 # of Injuries: 0 # of Hazmat Releases: 0 # of Hazmat Releases: 0 # of Fatalities: 0 # of Injuries: 0 # of Hazmat Releases: 0 # of Fatalities: 0 # of Fatalities: 0 # of Injuries: 0 # of Hazmat Releases: 0 # of Fatalities: 0 # of Fatalities: 0 # of Injuries: 0 # of Hazmat Releases: 0 # of Fatalities: 0 # of F																		
Cras	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																			
		#	# of Crashes:	0			# of Crashes with Fata	alities	<b>5:</b> 0			# of Cra	shes with	Injur	ries:	0		# of Tov	vaways:	0
# Not preventable:				0	# of Fatalit				<b>:</b> 0				# of	Injur	ries:	0	# of Hazmat Rele			0
Cras	sh Details (C	rashes listed r	epresent a d	r's involveme	ent ii	n FMCSA-reportable cr	ashe	es, wit	hout any	determ	ination as	to respo	nsib	bility.)						
Date DOT # Carrie			ier Na	ame		Driver Name		Drive	r Lic	State	Driver DO	B Rpt S	t Re	eport N	lumber	Location	# Fatalities	# of Inju	ıries	
	Inspection Activity (3 year history from MCMIS snapshot date)																			
Insp	ection Sum	mary																		
Driver Summary						Vehicle Summary					Hazmat Summary									
Driver Inspections:					1	Vehicle Inspections:					1	Hazmat Inspections							0	
Driver Out-of-service Inspections:						0	Vehicle Out-of-service Inspections:					0	Hazmat Out-of-service Inspections:							0
Driver Out-of-service Rate:						0%	Vehicle Out-of-service Rate:					0%	Hazmat Out-of-service Rate:							0%

Report executed at: 11/25/2024 3:17:37 PM

MCMIS snapshot date: 10/25/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details														
Carrie	r Info			Driver Info					Inspection Info					
	Date	DOT#	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol		
1	12/05/2023	2828543	ROYAL3 INC	RUIZ, TOLEDANO	R234541864450	FL	12/05/1986	KY	CV44623670	N	1	1		
Driver Violation: 392.16(a) Failing to use seat belt while operating a CMV NON-OOS														
Violati	Violation Summary													
Violation #				# of Violation	ons	# of Out-of-service Violations								
392.16(	a)	Failing to use	seat belt while operating a CMV	1						1		0		

The summary counts and rates only include violations that were attributable to TOLEDANO, MANUEL ALEJANDRO.

Report executed at: 11/25/2024 3:17:37 PM

MCMIS snapshot date: 10/25/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.