

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODRIGUEZF	ERNESTO F	R362206690950	FL										
RODRIGUEZ	ERNESTO	R362206690950	FL										
FRODRIGUEZ	ERNESTO F	R362206690950	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 7/28/2022 12:10:46 PM

MCMIS snapshot date: 06/24/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	09/28/2020	3355627	FIVE STAR LOGISTICS GROUP LLC	RODRIGUEZ, ERNESTO	R362206690950	FL	03/15/1969	KY	CV44371673	N	1	0
2	10/14/2020	3355627	FIVE STAR LOGISTICS GROUP LLC	RODRIGUEZ, ERNESTO	R362206690950	FL	03/15/1969	MO	W148005999	N	1	4
Vehicle Violation: 393.83(g) Exhaust leak under driver and/or sleeper compartment NON-OOS Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking Under Vehicle NON-OOS Vehicle Violation: 393.45(d) Brake Connections with Leaks Under Vehicle NON-OOS Vehicle Violation: 396.3(a)(1) Brake system pressure loss NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.83(g)	Exhaust leak under driver and/or sleeper compartment								1	0		
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle								1	0		
393.45(d)	Brake Connections with Leaks Under Vehicle								1	0		
396.3(a)(1)	Brake system pressure loss								1	0		

The summary counts and rates only include violations that were attributable to RODRIGUEZF, ERNESTO F.

Report executed at: 7/28/2022 12:10:46 PM

MCMIS snapshot date: 06/24/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>