

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
ANTONIOPRASLIN	LUIS ANTONIO	A5658130	CA										
PRASLINANTONIO	LUIS ANTONIO	A5658130	CA										
ANTONIO	LUIS ANTONIO	A5658130	CA										
PRASLIN	LUIS	A5658130	CA										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:	7			Vehicle Inspections:	5			Hazmat Inspections				0	
Driver Out-of-service Inspections:	0			Vehicle Out-of-service Inspections:	1			Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:	0%			Vehicle Out-of-service Rate:	20%			Hazmat Out-of-service Rate:				0%	

Report executed at: 6/21/2021 1:24:55 PM

MCMIS snapshot date: 05/28/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/06/2018	1315289	JAUREGUI TRUCKING INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	CA	A168562941	N	1	0
2	09/17/2018	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	OH	3261010187	N	2	1
Vehicle Violation: 393.75C Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS												
3	04/07/2019	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	AR	511C007382	N	2	1
Driver Violation: 392.2C Failure to obey traffic control device NON-OOS												
4	09/13/2019	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	OK	PE09171605	N	3	0
5	11/07/2019	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	MO	W210001474	N	2	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
6	02/02/2020	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS (co-driver)	A5658130	CA	06/13/1969	TN	TDOF000379	N	3	0
7	04/09/2021	2589359	MUSA LOGISTICS INC	PRASLIN, LUIS	A5658130	CA	06/13/1969	OH	1721002196	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.75C	Tire-other tread depth less than 2/32 of inch measured in a major tread groove								1	0		
392.2C	Failure to obey traffic control device								1	0		
393.75(a)(3)	Tire-flat and/or audible air leak								1	1		

The summary counts and rates only include violations that were attributable to ANTONIOPRASLIN, LUIS ANTONIO.

Report executed at: 6/21/2021 1:24:55 PM

MCMIS snapshot date: 05/28/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>