## **PSP Detailed Report**

## **Federal Motor Carrier Safety Administration**

					Driv	ver Inform	nation									
Last Name First Name						License #					State					
MANUEL ROBERT MANUEL					D03901691					AZ						
MANUELARMANDAREZ ROBERT MANUEL					D03901691					AZ						
ARMENDAREZMANUEL ROBERT MANUE									AZ							
							D03901691									
ARN	MENDAREZ			ROBERT	D03901691						AZ					
Crash Activity																
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																
# of Crashes:					# of Crashes with Fat	alities: 0		# of Crashes with I					waways: 1			
# Not preventable: 0					# of Fat	# of Fatalities: 0			# of I	njuries: 0	# of Hazmat Release					
Cra	sh Details (C	ashes listed i	epresent a dr	ver's involveme	ent in FMCSA-reportable c	rashes, wit	thout any	determ	ination as	to respon	sibility.)					
	Date	DOT#	Carrie	r Name	Driver Name	Drive	er Lic	State	Driver DO	B Rpt St	Report Number	r Location	# Fatalities	# Injuries		
1	02/02/2020	945634	LOGIST DISTRIBUTION	CS AND SERVICES INC	ARMENDAREZ, ROBERT	D0390	01691	AZ	02/04/196	9 CA	CA8252000030	RT395/350ft S SAND SHED RD	0	0		
Inspection Activity (3 year history from MCMIS snapshot date)																
Ins	pection Sumn	nary														
		Driver	Summary			Vehicle Summary					Hazmat Summary					
Driv	ver Inspections:				3 Vehicle Inspections:	Vehicle Inspections:			Hazmat Inspections							
Driver Out-of-service Inspections:					0 Vehicle Out-of-service In	Vehicle Out-of-service Inspections:			0	Hazmat Out-of-service Inspections:						
Driver Out-of-service Rate: 0%				0% Vehicle Out-of-service R	Vehicle Out-of-service Rate:			0%	Hazmat Out-of-service Rate:							

Report executed at: 5/21/2021 5:45:10 PM

MCMIS snapshot date: 04/30/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details														
Carrier Info				Driver Info					Inspection Info					
	Date	DOT#	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol		
1	01/31/2020	945634	LDS INC	ARMENDAREZ, ROBERT	D03901691	AZ	02/04/1969	NV	7116018589	N	2	1		
Vehicle Violation: 393.60(c) Damaged or discolored windshield NON-OOS														
2	08/14/2020	3033777	HICKORYTRANZ LLC	ARMENDAREZ, ROBERT	D03901691	AZ	02/04/1969	NM	3887214148	N	2	0		
3	04/09/2021	3516907	LEGAL TRUCKING INC	ARMENDAREZ, ROBERT	D03901691	AZ	02/04/1969	CA	NABI002723	N	1	0		
Violation Summary														
Violation #		Description									# of Out-of-service Violations			
393.60(c)		Damaged or discolored windshield										0		

The summary counts and rates only include violations that were attributable to MANUEL, ROBERT MANUEL.

Report executed at: 5/21/2021 5:45:10 PM

MCMIS snapshot date: 04/30/2021

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.