

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
ROSALESARRIOLA	CARLOS	R242113663650	FL										
ROSALES	CARLOS MANUEL	R242113663650	FL										
ARRIOLA	CARLOS MANUEL	R242113663650	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	07/18/2023	2836025	M & K TRANSPORT CORP	ROSALES, CARLOS	R242113663650	FL	10/05/1966	MS	MS3003230170	63	0	0	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	

Report executed at: 5/15/2024 3:32:57 PM

MCMIS snapshot date: 04/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/15/2022	2547117	X-PRESS FREIGHT LOGISTICS LLC	ROSALES ARRIOLA, CARLOS	R242113663650	FL	10/05/1966	FL	2939002850	N	3	0
2	09/12/2023	2836025	M & K TRANSPORT CORP	ROSALES ARRIOLA, CARLOS	R242113663650	FL	10/05/1966	CA	NDN7007141	N	1	7
<div> <div>Vehicle Violation:</div> <div>396.5(b)</div> <div>Hubs - Wheel seal leaking - inner wheel</div> <div>OOS</div> </div> <div> <div>Vehicle Violation:</div> <div>396.5(b)</div> <div>Hubs - Wheel seal leaking - inner wheel</div> <div>OOS</div> </div> <div> <div>Vehicle Violation:</div> <div>393.9(a)</div> <div>Inoperable head lamps</div> <div>NON-OOS</div> </div> <div> <div>Vehicle Violation:</div> <div>395.26(b)</div> <div>Motor carrier failed to ensure that the ELD automatically recorded the required data elements.</div> <div>NON-OOS</div> </div> <div> <div>Vehicle Violation:</div> <div>393.201(a)</div> <div>Frame cracked / loose / sagging / broken</div> <div>OOS</div> </div> <div> <div>Driver Violation:</div> <div>395.3(a)(3)(i)</div> <div>Driving beyond 11 hour driving limit. (Property Carrying Vehicle)</div> <div>NON-OOS</div> </div> <div> <div>Driver Violation:</div> <div>395.3(a)(3)(ii)</div> <div>Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes</div> <div>NON-OOS</div> </div>												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.5(b)	Hubs - Wheel seal leaking - inner wheel								2	2		
393.9(a)	Inoperable head lamps								1	0		
395.26(b)	Motor carrier failed to ensure that the ELD automatically recorded the required data elements.								1	0		
393.201(a)	Frame cracked / loose / sagging / broken								1	1		
395.3(a)(3)(i)	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)								1	0		
395.3(a)(3)(ii)	Driving beyond 8 hour driving limit since the end of the last on duty, off duty, or sleeper period of at least 30 minutes								1	0		

The summary counts and rates only include violations that were attributable to ROSALESARRIOLA, CARLOS.

Report executed at: 5/15/2024 3:32:57 PM

MCMIS snapshot date: 04/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>