

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information														
Last Name			First Name			License #			State					
TAPIA			BARTOLOME			T100060710820			FL					
Crash Activity														
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)														
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:			0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:			0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)														
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)														
Inspection Summary														
Driver Summary				Vehicle Summary				Hazmat Summary						
Driver Inspections:				4	Vehicle Inspections:				3	Hazmat Inspections			0	
Driver Out-of-service Inspections:				0	Vehicle Out-of-service Inspections:				2	Hazmat Out-of-service Inspections:			0	
Driver Out-of-service Rate:				0%	Vehicle Out-of-service Rate:				67%	Hazmat Out-of-service Rate:			0%	

Report executed at: 7/15/2022 9:52:21 PM

MCMIS snapshot date: 06/24/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/18/2021	3320451	TRUCKS INVESTMENTS LLC	TAPIA, BARTOLOME	T100060710820	FL	03/02/1971	CA	NBG7006007	N	1	8
Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS Vehicle Violation: 393.95(a) No/discharged/unsecured fire extinguisher NON-OOS Vehicle Violation: 393.60(c) Damaged or discolored windshield NON-OOS Vehicle Violation: 393.45(d) Brake connections with leaks or constrictions NON-OOS Vehicle Violation: 396.5(b) Oil and/or grease leak NON-OOS Vehicle Violation: 393.207(a) Axle positioning parts defective/missing NON-OOS Vehicle Violation: 396.3(a)(1) Brakes (general) Explain: NON-OOS Vehicle Violation: 396.5(b) Hubs - Wheel seal leaking - inner wheel NON-OOS												
2	01/02/2022	2156343	VS CARRIERS INC	TAPIA, BARTOLOME	T100060710820	FL	03/02/1971	MT	F663008419	N	2	1
Vehicle Violation: 393.45(b)(2) Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit OOS												
3	02/07/2022	2156343	VS CARRIERS INC	TAPIA, BARTOLOME	T100060710820	FL	03/02/1971	CO	0844001424	N	2	0
4	03/29/2022	2156343	VISTA TRANS	TAPIA, BARTOLOME	T100060710820	FL	03/02/1971	PA	C207208851	N	3	1
Driver Violation: 392.2 Failure to obey traffic control device NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.45	Brake tubing and hose adequacy								1	1		
393.95(a)	No/discharged/unsecured fire extinguisher								1	0		
393.60(c)	Damaged or discolored windshield								1	0		
393.45(d)	Brake connections with leaks or constrictions								1	0		
396.5(b)	Oil and/or grease leak								2	0		
393.207(a)	Axle positioning parts defective/missing								1	0		
396.3(a)(1)	Brakes (general) Explain:								1	0		
392.2	Failure to obey traffic control device								1	0		

Report executed at: 7/15/2022 9:52:21 PM

MCMIS snapshot date: 06/24/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	1
--------------	--	---	---

The summary counts and rates only include violations that were attributable to TAPIA, BARTOLOME.

Report executed at: 7/15/2022 9:52:21 PM

MCMIS snapshot date: 06/24/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.