PSP Detailed Report

Federal Motor Carrier Safety Administration

				Driv	ver Info	orma	ation																	
Last Name		Fi	st Name		Licens	se #					State													
PEREZMARQUEZ		PE	DRO		P6256	P625675770470						FL												
PABLOPEREZMAR	PABLOPEREZMARQUEZ PEDRO PABLO				P625675770470						FL													
MARQUEZPEREZ		PE	DRO PABLO		P6256	6757	70470				FL													
MARQUEZ			PEDRO PABLO			P625675770470					FL													
PEREZMARQUEZ			PEDRO PABLO			P625675770470					FL													
PABLO		PE	DRO PABLO		P6256	6757	70470		FL															
PEREZMARQUEZPABLO			DRO PABLO	P6256	P625675770470						FL													
				С	rash Ac	ctiv	vity																	
Crash Summary	(Crashes liste	d represent a di	iver's involveme	nt in FMCSA-reportable	e crashe	es, v	without any	dete	rmination a	as to resp	onsib	ility.)												
	#	# of Crashes: 0		alities:	ies: 0 # of Crashes with					h Injuries: 0 # of Towaways:					0									
	# Not	preventable: 0		alities:	s: 0 # of					Injuries: 0 # of Hazmat Releas				eleases:	0									
Crash Details (C	crashes listed r	epresent a drive	r's involvement i	in FMCSA-reportable c	rashes, v	with	hout any de	etermi	ination as	to respon	sibilit	y.)					_							
Date	DOT #	Carrier N	lame	Driver Name	Dr	river	Lic	State	Driver DO	B Rpt St	Repo	rt Nun	nber	Location	# Fatalities	# Inju	ries							
			Inspe	ction Activity (3 year	r histor	ry fr	rom MCMI	S sn	apshot da	ate)														
Inspection Sum	mary																							
	Driver	Summary			Vehicle S	Sumr	mary						Ha	azmat Summa	ry									
Driver Inspections	5:		1	Vehicle Inspections:					1	Hazmat Ins	spectio	ns					0							
Driver Out-of-service Inspections:				Vehicle Out-of-service Inspections:				1	Hazmat Out-of-service Inspections:							0								
Driver Out-of-serv	rice Rate:		100%	Vehicle Out-of-service Ra	ate:				100%	Hazmat Ou	ut-of-se	rvice	Rate:	:			0%							

Report executed at: 3/24/2022 11:53:19 AM

MCMIS snapshot date: 02/25/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details															
Carrier Info				D	Driver Info					Inspection Info					
	Date	DOT #	Carrier Name		Driver Name	Driver Lic	r Lic State D		Rpt St Report Numb		Hazmat Insp	Insp Level	# of Viol		
1	05/24/2021	3219126	MILCA FREIGHT LL	C P	PEREZ MARQUEZ, PEDRO	P625675770470	FL	02/07/1977	CA	UEFG001333	N	2	3		
	Driver Violation: 392.2 State/Local Laws - Speeding 15 or more miles per hour over the speed limit. NON-OOS														
Driver Violation: 395.8(e)(1) False				False re	e report of drivers record of duty status OOS										
Vehicle Violation: 392.9(a)(1) Failin 393.1					g to secure cargo as specified in 49 CFR 393.100 through OOS										
Violati	on Summary														
Violation #					Description					# of Violati	ons	# of Out-of-service Violations			
392.2		State/Local Laws - Speeding 15 or more miles per hour over the speed limit. 1									0				
395.8(e)	(1)	False report of drivers record of duty status 1									1				
392.9(a)	(1)	Failing to secure cargo as specified in 49 CFR 393.100 through 393.142 1									1				

The summary counts and rates only include violations that were attributable to PEREZMARQUEZ, PEDRO.

Report executed at: 3/24/2022 11:53:19 AM MCMIS snapshot date: 02/25/2022 This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.