

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RAUDEL	FERNANDEZ	ANTHONY RAUDEL	F655016920890	FL									
RAUDEL	FERNANDEZ	ANTHONY RAUDEL	F655016920890	FL									
FERNANDEZ	RAUDEL	ANTHONY RAUDEL	F655016920890	FL									
FERNANDEZ	RAUDEL	ANTHONY	F655016920890	FL									

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
1	07/07/2021	3142640	R A L TRUCKING CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	FL	FL8370251501	POINCIANA BLVD	0	0	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		13		Vehicle Inspections:		7		Hazmat Inspections				0	
Driver Out-of-service Inspections:		5		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		38%		Vehicle Out-of-service Rate:		14%		Hazmat Out-of-service Rate:				0%	

Report executed at: 6/8/2023 9:40:11 AM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/10/2020		A.E.R. TRANSPORT, INC	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	FL	3635005658	N	2	4
Vehicle Violation: 393.60(d) Glazing permits < 70% of light NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.71(h)(10) No or Improper safety chains for towbar OOS Vehicle Violation: 393.17 No/defective lamp/reflector-towaway operation OOS												
2	05/17/2021	3142640	R A L TRUCKING CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	PA	XL00025403	N	3	3
Driver Violation: 395.8(k)(2) Driver failing to retain previous 7 days records of duty status OOS Driver Violation: 392.2 Unlawfully parking and/or leaving vehicle in the roadway NON-OOS Driver Violation: 395.22(h)(4) Driver failed to maintain supply of blank drivers records of duty status graph-grids NON-OOS												
3	07/12/2021	3142640	R A L TRUCKING CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	OH	3235007963	N	2	6
Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Vehicle Violation: 392.2 IRP Apportioned Tag or Registration Violation NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.13(c)(2) No Lower Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993 NON-OOS Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS												

Report executed at: 6/8/2023 9:40:11 AM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

4	10/03/2021	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	AZ	0306113071	N	2	10
Vehicle Violation: 392.2 Wheel (Mud) Flaps missing or defective NON-OOS Vehicle Violation: 393.11 Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 393.11 No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993 NON-OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS Driver Violation: 395.24(c)(2)(iii) Driver failed to manually add shipping document number NON-OOS Driver Violation: 395.24(c)(2)(ii) Driver failed to manually add the trailer number NON-OOS												
5	03/08/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	FL	1952003290	N	3	1
Vehicle Violation: 392.2 State or International Fuel Tax (IFTA) Violation NON-OOS												
6	06/16/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	NV	7143019567	N	2	4
Driver Violation: 395.34(a)(1) Failing to note malfunction that requires use of paper log NON-OOS Driver Violation: 395.22(h)(4) Driver failed to maintain supply of blank drivers records of duty status graph-grids NON-OOS Driver Violation: 395.24(d) ELD cannot transfer ELD records electronically NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS												
7	08/09/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	WA	W341000433	N	3	0
8	08/11/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	WA	W602011742	N	3	1
Driver Violation: 383.51(a) Driving a CMV while CDL is suspended for a safety-related or unknown reason and in state of driver's license issuance. OOS												
9	08/12/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	MT	H661000379	N	3	0
10	09/21/2022	3710725	LK TRUCKING SERVICE CORP	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	VA	6937001672	N	3	0

Report executed at: 6/8/2023 9:40:11 AM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

11	11/06/2022	3598717	INSPIRE LB INC	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	IA	000TT83L0N	N	2	0
12	01/06/2023	3598717	INSPIRE LB INC	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	WI	2799000254	N	2	2
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status				OOS					
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status				OOS					
13	02/07/2023	3598717	INSPIRE LB INC	FERNANDEZ, ANTHONY	F655016920890	FL	03/09/1992	OK	PE12004922	N	2	0

#### Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
392.2	State or International Fuel Tax (IFTA) Violation	4	0
395.34(a)(1)	Failing to note malfunction that requires use of paper log	1	0
395.22(h)(4)	Driver failed to maintain supply of blank drivers records of duty status graph-grids	2	0
395.24(d)	ELD cannot transfer ELD records electronically	1	0
393.9(a)	Inoperative turn signal	5	0
393.60(d)	Glazing permits < 70% of light	1	0
393.71(h)(10)	No or Improper safety chains for towbar	1	1
393.17	No/defective lamp/reflector-towaway operation	1	1
396.17(c)	Operating a CMV without proof of a periodic inspection	2	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	2	0
393.13(c)(2)	No Lower Rear retroreflective sheeting or reflex reflective material as required for vehicles manufactured before December 1993	1	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	2	2
395.8(e)(1)	False report of drivers record of duty status	2	2
393.11	Truck-Tractor lower rear mud flaps retroreflective sheeting / reflex reflective material requirements for vehicles manufactured after July 1997	2	0
395.24(c)(2)(iii)	Driver failed to manually add shipping document number	1	0
395.24(c)(2)(ii)	Driver failed to manually add the trailer number	1	0
383.51(a)	Driving a CMV while CDL is suspended for a safety-related or unknown reason and in state of driver's license issuance.	1	1
395.8(k)(2)	Driver failing to retain previous 7 days records of duty status	1	1

The summary counts and rates only include violations that were attributable to RAUDEL FERNANDEZ, ANTHONY RAUDEL.

Report executed at: 6/8/2023 9:40:11 AM

MCMIS snapshot date: 05/26/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>