PSP Detailed Report

Federal Motor Carrier Safety Administration

					Driv	ver Inf	form	ation										
Last Name			Firs	st Name		Lice	License #				State							
RODRIGUEZALVAREZ				OSNIEL F			R362640832500				FL							
RODRIGUEZ				OSNIEL I			R362640832500				FL							
ALVAREZRODRIGUEZ OF				OSNIEL F			R362640832500					FL						
ALVAREZ OS				INIEL		R36	R362640832500			FL								
Crash Activity																		
Crash Summar	Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
# of Crashes:			0		# of Crashes with Fata	of Crashes with Fatalities: 0 # of Crashes with				es with Ir	njuries:	0	# of Tow			vaways:	0	
	# Not	preventable:	0		# of Fatalities: 0 # of				# of Ir	njuries:	0	# of Hazmat Relea			eleases:	0		
Crash Details (Crashes listed r	epresent a c	Irive	r's involvement i	n FMCSA-reportable cr	rashes	s, wit	hout any d	eterm	ination as to	respon	sibility	'.)					
Date DOT # Carrie			ier N	ame	Driver Name	Driver Lic		State	Driver DOB	Rpt St Report Number		er Locatio	on #Fa	# Fatalities # of Injuries		uries		
				Inspe	ction Activity (3 year	r histo	ory fi	rom MCM	IS sn	apshot dat	e)							
Inspection Sum	mary																	
Driver Summary					Vehicle Summary					Hazmat Summary								
Driver Inspections:					Vehicle Inspections: 2				2 H	2 Hazmat Inspections						0		
Driver Out-of-serv	vice Inspections:			0	Vehicle Out-of-service Inspections: 1 Hazmat				azmat Ou	at Out-of-service Inspections:						0		
Driver Out-of-service Rate:					Vehicle Out-of-service Rate:					50% H	Hazmat Out-of-service Rate:					0%		

Report executed at: 11/1/2022 2:19:25 PM

MCMIS snapshot date: 09/30/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspec	tion Details											
Carrie	r Info			Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	10/19/2019	2726429	COBB TRANSPORTATION INC	RODRIGUEZ ALVAREZ, OSNIEL	R362640832500	FL	07/10/1983	AR	569E003377	N	3	0
2	11/10/2019	2726429	COBB TRANSPORTATION INC	RODRIGUEZ ALVAREZ, OSNIEL	R362640832500	FL	07/10/1983	CA	ND64000922	N	1	4
	Vehicle \ Vehicle \ Vehicle \ Vehicle \	/iolation: /iolation:	396.5(b) Hubs 393.47(e) Clamp 203.52(b) CMV	rable Required Lamp - Wheel seal leaking - inner wheel o or Roto type brake out-of-adjustment manufactured after 10/19/94 has an automa ment system that fails to compensate for we		NON-C NON-C NON-C	oos oos					
3	02/28/2020	3007855	ROADTEX FREIGHT SYSTEMS LLC	RODRIGUEZ ALVAREZ, OSNIEL	R362640832500	FL	07/10/1983	AZ	0238K1NBJ4	N	3	2
Driver Violation: 205 8/b)(5) Drive			205 8(b)(5) Driver	g to use seat belt while operating a CMV r failed to appropriately indicate location and remarks for ges in duty status.			NON-OOS NON-OOS					
4	06/04/2020	3007855	ROADTEX FREIGHT SYSTEMS LLC	RODRIGUEZ ALVAREZ, OSNIEL	R362640832500	FL	07/10/1983	WA	W604009162	N	3	3
	Driver Vi	olation:	392.2 Failur	e to obey traffic control device		NON-C	OS					
	Driver Vi	olation:		er cannot read or speak the English language sufficiently to Nond to official inquiries.			NON-OOS					
	Driver Vi			ion of Local Laws - Explain:		NON-C						
5	06/15/2020	3007855	ROADTEX FREIGHT SYSTEMS LLC	RODRIGUEZ ALVAREZ, OSNIEL	R362640832500	FL	07/10/1983	ОН	1251007303	N	3	2
	Driver Vi	olation:	392.2 Failur	e to obey traffic control device		NON-C	OS					
			392.2 State/ limit.	/Local Laws - Speeding 6-10 miles per hour over the speed			NON-OOS					
6	11/23/2020	3119062	RIKI TRANSPORTATION INC	OSNIEL, RODRIGUEZ	R362640832500	FL	07/10/1983	TN	BBAN023627	N	3	0

Report executed at: 11/1/2022 2:19:25 PM

MCMIS snapshot date: 09/30/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

	7 (9/27/2022	1876301	MCI XPRESS	RODRIGUEZ ALVEREZ, OSNIEL	R362640832500	FL	07/10/1983	OK	PE05173010	Ν	1	6
	Driver Violation:		plation:	391.11(b)(2)	Driver cannot read or speak the English languation respond to official inquiries.	ge sufficiently to	NON-OOS						
	Driver Violation:		plation:	395.24(d)	ELD cannot transfer ELD records electronically			NON-OOS					
	Vehicle Violation:		iolation:	393.9(a)	Inoperable head lamps		NON-C	OOS					
	Vehicle Violation:		iolation:	393.75(a)(3)	Tire-flat and/or audible air leak			OOS					
	Vehicle Violation:		iolation:	393.45(d)	Brake Connections with Leaks Under Vehicle		NON-C	OOS					
	Vehicle Violation:		iolation:	393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking L	nder Vehicle	C	OOS					
Vic	lation	Summary											

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations	
392.2	Failure to obey traffic control device	4	0	
391.11(b)(2)	Driver cannot read or speak the English language sufficiently to respond to official inquiries.	2	0	
395.24(d)	ELD cannot transfer ELD records electronically	1	0	
393.9(a)	Inoperable head lamps	2	0	
393.75(a)(3)	Tire-flat and/or audible air leak	1	1	
393.45(d)	Brake Connections with Leaks Under Vehicle	1	0	
393.45(b)(2)	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	1	
396.5(b)	Hubs - Wheel seal leaking - inner wheel	1	0	
393.47(e)	Clamp or Roto type brake out-of-adjustment	1	0	
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0	
392.16(a)	Failing to use seat belt while operating a CMV	1	0	
395.8(h)(5)	Driver failed to appropriately indicate location and remarks for changes in duty status.	1	0	

The summary counts and rates only include violations that were attributable to RODRIGUEZALVAREZ, OSNIEL.

Report executed at: 11/1/2022 2:19:25 PM

MCMIS snapshot date: 09/30/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.