

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
TAMAYO	REIDYS	50024617	TX										
TAMAYO	REIDYS	R535720883430	FL										
ROMAYTAMAYO	REIDYS	50024617	TX										
ROMAY	REIDYS	50024617	TX										
ROMAY	REIDYS	R535720883430	FL										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		1		Vehicle Inspections:		1		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	

Report executed at: 7/15/2024 12:11:01 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	02/21/2024	1941898	ALAMO TRANSIT COMPANY	ROMAY TAMAYO, REIDYS	50024617	TX	09/23/1988	TX	V241321962	N	2	2
Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS												
Vehicle Violation: 393.45 Brake tubing and hose adequacy NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.45	Brake tubing and hose adequacy								2	1		

The summary counts and rates only include violations that were attributable to TAMAYO, REIDYS.

Report executed at: 7/15/2024 12:11:01 PM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.