

PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information | | | | | | | | | | | | | |
|--|------------|-------------------------------|-------------------------------------|-----------------------------|------------|------------------------------------|------------|----------------|---------------|----------|--------------|---------------|--|
| Last Name | First Name | License # | State | | | | | | | | | | |
| CRUZ | LUIS IVAN | B626529904600 | FL | | | | | | | | | | |
| BERRIOSCRUZ | LUIS | B626529904600 | FL | | | | | | | | | | |
| BERRIOS | LUIS IVAN | B626529904600 | FL | | | | | | | | | | |
| Crash Activity | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | |
| # of Crashes: | 0 | # of Crashes with Fatalities: | 0 | # of Crashes with Injuries: | 0 | # of Towaways: | 0 | | | | | | |
| # Not preventable: | 0 | # of Fatalities: | 0 | # of Injuries: | 0 | # of Hazmat Releases: | 0 | | | | | | |
| Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Location | # Fatalities | # of Injuries | |
| Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | |
| Inspection Summary | | | | | | | | | | | | | |
| Driver Summary | | | | Vehicle Summary | | | | Hazmat Summary | | | | | |
| Driver Inspections: | | 4 | Vehicle Inspections: | | 1 | Hazmat Inspections | | 0 | | | | | |
| Driver Out-of-service Inspections: | | 1 | Vehicle Out-of-service Inspections: | | 0 | Hazmat Out-of-service Inspections: | | 0 | | | | | |
| Driver Out-of-service Rate: | | 25% | Vehicle Out-of-service Rate: | | 0% | Hazmat Out-of-service Rate: | | 0% | | | | | |

Report executed at: 4/22/2024 2:48:49 PM

MCMIS snapshot date: 04/04/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| Inspection Details | | | | | | | | | | | | |
|---|--|---------|--------------------|--------------------|---------------|-------|------------|-----------------|-----------------|--------------------------------|------------|-----------|
| Carrier Info | | | | Driver Info | | | | Inspection Info | | | | |
| | Date | DOT # | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol |
| 1 | 01/16/2023 | 3063897 | CIRCLE O INC | BERRIOS CRUZ, LUIS | B626529904600 | FL | 12/20/1990 | GA | 1410000337 | N | 3 | 8 |
| Driver Violation: 392.82(a)(1) Using a hand-held mobile telephone while operating a CMV NON-OOS Driver Violation: 392.2 Lane Restriction violation NON-OOS Driver Violation: 395.22(h)(1) Driver failing to maintain ELD user's manual NON-OOS Driver Violation: 395.22(h)(3) Driver failed to maintain instruction sheet for ELD malfunction reporting requirements NON-OOS Driver Violation: 395.24(d) ELD cannot transfer ELD records electronically NON-OOS Driver Violation: 395.22(h)(4) Driver failed to maintain supply of blank drivers records of duty status graph-grids NON-OOS Driver Violation: 395.24(c)(2)(ii) Driver failed to manually add the trailer number NON-OOS Driver Violation: 395.24(c)(2)(iii) Driver failed to manually add shipping document number NON-OOS | | | | | | | | | | | | |
| 2 | 03/14/2023 | 3290597 | BILLYS TOYS LLC | BERRIOS CRUZ, LUIS | B626529904600 | FL | 12/20/1990 | FL | 4516000697 | N | 2 | 2 |
| Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS Vehicle Violation: 396.17(c) Operating a CMV without proof of a periodic inspection NON-OOS | | | | | | | | | | | | |
| 3 | 07/15/2023 | 2525862 | ZUES LLC | BERRIOS CRUZ, LUIS | B626529904600 | FL | 12/20/1990 | MT | H661001317 | N | 3 | 1 |
| Driver Violation: 395.8(e)(1) False report of drivers record of duty status OOS | | | | | | | | | | | | |
| 4 | 11/21/2023 | 2913060 | C V P TRUCKING LLC | BERRIOS CRUZ, LUIS | B626529904600 | FL | 12/20/1990 | LA | LACK013195 | N | 3 | 1 |
| Driver Violation: 390.17 Operating a CMV while using additional equipment and accessories that decreases the safety of operation NON-OOS | | | | | | | | | | | | |
| Violation Summary | | | | | | | | | | | | |
| Violation # | Description | | | | | | | | # of Violations | # of Out-of-service Violations | | |
| 392.82(a)(1) | Using a hand-held mobile telephone while operating a CMV | | | | | | | | 1 | 0 | | |
| 392.2 | Lane Restriction violation | | | | | | | | 1 | 0 | | |
| 395.22(h)(1) | Driver failing to maintain ELD user's manual | | | | | | | | 1 | 0 | | |
| 395.22(h)(3) | Driver failed to maintain instruction sheet for ELD malfunction reporting requirements | | | | | | | | 1 | 0 | | |
| 395.24(d) | ELD cannot transfer ELD records electronically | | | | | | | | 1 | 0 | | |
| 395.22(h)(4) | Driver failed to maintain supply of blank drivers records of duty status graph-grids | | | | | | | | 1 | 0 | | |
| 395.24(c)(2)(ii) | Driver failed to manually add the trailer number | | | | | | | | 1 | 0 | | |

Report executed at: 4/22/2024 2:48:49 PM

MCMIS snapshot date: 04/04/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| | | | |
|-------------------|---|---|---|
| 395.24(c)(2)(iii) | Driver failed to manually add shipping document number | 1 | 0 |
| 393.78 | Windshield wipers inoperative/defective | 1 | 0 |
| 396.17(c) | Operating a CMV without proof of a periodic inspection | 1 | 0 |
| 395.8(e)(1) | False report of drivers record of duty status | 1 | 1 |
| 390.17 | Operating a CMV while using additional equipment and accessories that decreases the safety of operation | 1 | 0 |

The summary counts and rates only include violations that were attributable to CRUZ, LUIS IVAN.

Report executed at: 4/22/2024 2:48:49 PM

MCMIS snapshot date: 04/04/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.