

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
JUAREZ		HECTOR		J620320791670			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		10		Vehicle Inspections:		6		Hazmat Inspections				0			
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		20%		Vehicle Out-of-service Rate:		17%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	06/30/2020	2975712	VIKING TRANSPORTATION INC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	AR	588E001825	N	2	1			
Vehicle Violation:		393.9(a)		Inoperable head lamps		NON-OOS									

Report executed at: 5/4/2023 11:59:01 AM

MCMIS snapshot date: 03/31/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	07/09/2020	3395612	CAMBLOR TRANSPORT LLC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	FL	1934004568	N	2	9
Driver Violation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS Vehicle Violation: 392.2 State/Local Laws - Excessive weight - More than 5000 lbs over on an axle/axle groups. NON-OOS Vehicle Violation: 392.2 State/Local Laws - Excessive weight - 2501-5000 lbs over on allowable gross weight NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.11 Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997 NON-OOS Vehicle Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories OOS Vehicle Violation: 396.5(b) Hubs - oil and/or Grease Leaking from hub - outer wheel OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.75(c) Tire-other tread depth less than 2/32 of inch measured in a major tread groove NON-OOS												
3	08/19/2020	2010443	LD RODRIGUEZ TRANSPORT LLC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	TX	5TC70XKUPK	N	2	3
Vehicle Violation: 393.67(c)(7)(v) Fuel tank fill pipe cap missing NON-OOS Vehicle Violation: 393.209(e) Power steering violations NON-OOS Vehicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS												
4	10/28/2020	3118314	SERVICE & LOGISTICS MULTINATIONAL CORPORATION	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	SD	0020081076	N	3	1
Driver Violation: 392.2 State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups. NON-OOS												
5	03/23/2021	3118314	SERVICE & LOGISTICS MULTINATIONAL CORPORATION	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	WY	LCDT000224	N	3	1
Driver Violation: 392.2 State/Local Laws - Speeding 6-10 miles per hour over the speed limit. NON-OOS												
6	10/03/2021	3274703	GALIANOS FREIGHT INC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	OR	AASS007725	N	3	2
Driver Violation: 395.8(e)(1) False Record of Duty Status - Improper use of Personal Conveyance Exception OOS Driver Violation: 395.8(e)(1) False Record of Duty Status - Improper use of Personal Conveyance Exception OOS												
7	03/18/2022	3274703	GALIANOS FREIGHT INC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	IL	4004410147	N	3	0
8	04/05/2022	3428325	FALCON LOGISTICS GROUP LLC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	NC	0006407857	N	2	1
Driver Violation: 395.24(d) ELD cannot transfer ELD records electronically NON-OOS												

Report executed at: 5/4/2023 11:59:01 AM

MCMIS snapshot date: 03/31/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

9	07/04/2022	3851880	DSM LOGISTIC TRANSPORT CORP	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	FL	2525004998	N	2	2
Vehicle Violation:		392.2	State Insurance Violation		NON-OOS							
Vehicle Violation:		393.78	Windshield wipers inoperative/defective		NON-OOS							
10	01/26/2023	3649003	MIAMEX INC	JUAREZ, HECTOR	J620320791670	FL	05/07/1979	MO	A4S4006195	N	2	7
Vehicle Violation:		393.60(d)	Glazing permits < 70% of light		NON-OOS							
Vehicle Violation:		393.60(e)	Windshield - Obstructed		NON-OOS							
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998		NON-OOS							
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status		NON-OOS							
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status		NON-OOS							
Driver Violation:		395.8(e)(1)	False report of drivers record of duty status		NON-OOS							
Driver Violation:		395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD		NON-OOS							

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.67(c)(7)(v)	Fuel tank fill pipe cap missing	1	0
393.209(e)	Power steering violations	1	0
393.78	Windshield wipers inoperative/defective	2	0
392.2	State/Local Laws - Excessive weight - 2501-5000 lbs over on an axle/axle groups.	5	0
395.8(e)(1)	False Record of Duty Status - Improper use of Personal Conveyance Exception	5	2
393.60(d)	Glazing permits < 70% of light	1	0
393.60(e)	Windshield - Obstructed	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
395.30(b)(1)	Driver failed to certify the accuracy of the information gathered by the ELD	1	0
395.24(d)	ELD cannot transfer ELD records electronically	1	0
393.9(a)	Inoperable head lamps	3	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1
393.11	Truck-Tractor upper body corner requirements for retroreflective sheeting or reflex reflective material for vehicles manufactured after July 1997	1	0
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories	1	1
396.5(b)	Hubs - oil and/or Grease Leaking from hub - outer wheel	1	1
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	1	0

The summary counts and rates only include violations that were attributable to JUAREZ, HECTOR.

Report executed at: 5/4/2023 11:59:01 AM

MCMIS snapshot date: 03/31/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>