

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
NEVAREZANGEL	JOSE ANGEL	N162421924210	FL										
NEVAREZ	JOSE	N162421924210	FL										
ANGELNEVAREZ	JOSE ANGEL	N162421924210	FL										
ANGEL	JOSE ANGEL	N162421924210	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		3		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 8/27/2023 5:35:01 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/16/2020	3048083	VANNER INC	NEVAREZ, JOSE (co-driver)	N162421924210	FL	11/21/1992	WA	W203006169	N	2	0
2	11/08/2021	1730271	A F F TRANS LLC	NEVAREZ, JOSE	N162421924210	FL	11/21/1992	MD	2395000107	N	3	0
3	12/29/2021	1273551	BONUS TRANSPORTATION LLC	NEVAREZ, JOSE	N162421924210	FL	11/21/1992	AR	706C001653	N	2	1
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.75(a)(3)	Tire-flat and/or audible air leak								1	1		

The summary counts and rates only include violations that were attributable to NEVAREZANGEL, JOSE ANGEL.

Report executed at: 8/27/2023 5:35:01 PM

MCMIS snapshot date: 07/28/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.