

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name	First Name			License #			State								
HERNANDEZ	YOSVANI			40243156			TX								
HERNANDEZ	YOSVANI			H655960780040			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		1		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%			

Report executed at: 1/2/2025 3:57:56 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	04/13/2022	3453780	C & Y TRANSPORTATION INC	HERNANDEZ, YOSVANI	H655960780040	FL	01/04/1978	MS	1013011050	N	2	2
Vehicle Violation: 393.9(a) Inoperable Required Lamp OOS Driver Violation: 395.8(e)(1) False Record of Duty Status - Improper use of Personal Conveyance Exception NON-OOS												
2	05/03/2023	3453780	C & Y TRANSPORTATION INC	HERNANDEZ, YOSVANI	H655960780040	FL	01/04/1978	FL	1581006183	N	3	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.9(a)	Inoperable Required Lamp								1	1		
395.8(e)(1)	False Record of Duty Status - Improper use of Personal Conveyance Exception								1	0		

The summary counts and rates only include violations that were attributable to HERNANDEZ, YOSVANI.

Report executed at: 1/2/2025 3:57:56 PM

MCMIS snapshot date: 11/29/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>