

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
ARNOLD	KENNETH ARNOLD	009068527	LA										
HATHORN	KENNETH	009068527	LA										
ARNOLDHATHORN	KENNETH ARNOLD	009068527	LA										
HATHORNARNOLD	KENNETH ARNOLD	009068527	LA										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		1	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		1		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# Injuries	
1	02/01/2021	75525	DART TRANSIT COMPANY	HATHORN, KENNETH	009068527	LA	02/07/1967	LA	LA1185755936	US-165	0	0	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		6		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		1		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		17%		Vehicle Out-of-service Rate:		100%		Hazmat Out-of-service Rate:				0%	

Report executed at: 5/11/2022 10:32:49 AM

MCMIS snapshot date: 04/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	08/16/2019	1926183	IHR TRANSPORT	HATHORN, KENNETH	009068527	LA	02/07/1967	TX	5J3F0VBFUZ	N	2	5
Vehicle Violation: 396.5(b) Oil and/or grease leak NON-OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak NON-OOS												
2	12/01/2019	1926183	IHR TRANSPORT	HATHORN, KENNETH	009068527	LA	02/07/1967	LA	LANP000497	N	3	1
Driver Violation: 395.22(g) Portable ELD not mounted in a fixed position and visible to driver NON-OOS												
3	02/21/2020	75525	DART TRANSIT COMPANY	HATHORN, KENNETH	009068527	LA	02/07/1967	NC	0006175485	N	3	0
4	08/11/2020	75525	DART TRANSIT COMPANY	HATHORN, KENNETH	009068527	LA	02/07/1967	AL	1180000144	N	3	0
5	10/25/2021	2953404	DART X INC	HATHORN, KENNETH	009068527	LA	02/07/1967	MS	U051001755	N	3	0
6	12/01/2021	2953404	DART X INC	HATHORN, KENNETH	009068527	LA	02/07/1967	AL	1712001084	N	2	5
Vehicle Violation: 390.21T(a) CMV not marked in accordance with regulations NON-OOS Vehicle Violation: 393.95(f) No / insufficient warning devices NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS Vehicle Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON-OOS Driver Violation: 395.8(k)(2) Driver failing to retain previous 7 days records of duty status OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.5(b)	Oil and/or grease leak								1	0		
393.45	Brake tubing and hose adequacy								1	1		
393.75(a)(3)	Tire-flat and/or audible air leak								4	2		

Report executed at: 5/11/2022 10:32:49 AM

MCMIS snapshot date: 04/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

390.21T(a)	CMV not marked in accordance with regulations	1	0
393.95(f)	No / insufficient warning devices	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
395.8(k)(2)	Driver failing to retain previous 7 days records of duty status	1	1
395.22(g)	Portable ELD not mounted in a fixed position and visible to driver	1	0

The summary counts and rates only include violations that were attributable to ARNOLD, KENNETH ARNOLD.

Report executed at: 5/11/2022 10:32:49 AM

MCMIS snapshot date: 04/29/2022

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.