PSP Detailed Report

Federal Motor Carrier Safety Administration

| Driver Information Last Name First Name License # State | | | | | | | | | | | | | | | | | | |
|--|--|-------|-----------|-------|-------------------------------------|------------------|---|----------------|----------|-----------------------------|------------------------------------|-------------|----------------|---|----------|--------------|-----------|-------|
| Last Name First Name | | | | | License # | | | | | | State | | | | | | | |
| HATHORN KENNETH | | | | | | 009068527 | | | | | LA | | | | | | | |
| | Crash Activity | | | | | | | | | | | | | | | | | |
| Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | | | | |
| # of Crashes: 1 | | | | 1 | # of Crashes with Fataliti | | | 0 | | | # of Cras | shes with I | njuries: | 0 | | /aways: | 1 | |
| #Not preventable: 0 #of Fatalities: 0 #of Injuries: 0 #of Hazmat | | | | | | | | # of Hazmat Re | eleases: | 0 | | | | | | | | |
| Cras | Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.) | | | | | | | | | | | | | | | | | |
| | Date | DOT# | Carri | er Na | ame | Driver Name | | Drive | r Lic | State | Driver DOI | B Rpt St | Report Number | | Location | # Fatalities | # of Inju | uries |
| 1 | 02/01/2021 | 75525 | DART TRAN | ISIT | COMPANY | HATHORN, KENNETH | (| 00906 | 8527 | LA | 02/07/1967 | 7 LA | A LA1185755936 | | US-165 | 0 | 0 | |
| | Inspection Activity (3 year history from MCMIS snapshot date) | | | | | | | | | | | | | | | | | |
| Insp | ection Sumi | nary | | | | | | | | | | | | | | | | |
| Driver Summary | | | | | Vehicle Summary | | | | | Hazmat Summary | | | | | | | | |
| Driver Inspections: 6 | | | | | Vehicle Inspections: | | | | | 2 | Hazmat Inspections | | | | | | 0 | |
| Driver Out-of-service Inspections: | | | | | Vehicle Out-of-service Inspections: | | | | | 2 | Hazmat Out-of-service Inspections: | | | | | | 0 | |
| Driver Out-of-service Rate: | | | | 17% | Vehicle Out-of-service Rate: | | | | 100% | Hazmat Out-of-service Rate: | | | | | | 0% | | |

Report executed at: 6/14/2022 9:59:54 AM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| Inspection Details | | | | | | | | | | | | | |
|--------------------------------------|---------------------------------------|---|---|---|--|-----------------------------------|------------|---------|-----------------|----------------|------------|--------------|--|
| Carrier | r Info | | | Driver Info | | | | | Inspection Info | | | | |
| | Date | DOT# | Carrier Name | Driver Name | Driver Lic | State | Driver DOB | Rpt St | Report Number | Hazmat Insp | Insp Level | # of Viol | |
| 1 | 08/16/2019 | 1926183 | IHR TRANSPORT | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | TX | 5J3F0VBFUZ | N | 2 | 5 | |
| | Vehicle Violation: 396.5(b) Oil and | | | d/or grease leak | | | | | | | | | |
| | Vehicle Violation: 393.45 Brak | | | tubing and hose adequacy | | | | | | | | | |
| | Vehicle Violation: 393.75(a)(3) Tire | | 393.75(a)(3) Tire-fl | lat and/or audible air leak OOS | | | | | | | | | |
| | Vehicle Violation: 393.75(a)(3) Tire | | | at and/or audible air leak | | | | | | | | | |
| | Vehicle Violation: 393 | | 393.75(a)(3) Tire-fl | Tire-flat and/or audible air leak | | | os | | | | | | |
| 2 | 12/01/2019 | 1926183 | IHR TRANSPORT | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | LA | LANP000497 | N | 3 | 1 | |
| | Driver Violation: 395.22(g) Portal | | | ble ELD not mounted in a fixed position and | le ELD not mounted in a fixed position and visible to driver NON-OOS | | | | | | | | |
| 3 | 02/21/2020 75525 DART TRANSIT COMPANY | | DART TRANSIT COMPANY | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | NC | 0006175485 | N | 3 | 0 | |
| | | | | | | | | | | | | | |
| 4 | 08/11/2020 | 75525 | DART TRANSIT COMPANY | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | AL | 1180000144 | N | 3 | 0 | |
| | | | • | | | • | | | | | • | | |
| 5 | 5 10/25/2021 2953404 | | DART X INC | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | MS | U051001755 | N | 3 | 0 | |
| | | | | | | ! | | | | | | | |
| 6 | 12/01/2021 | 2953404 | DART X INC | HATHORN, KENNETH | 009068527 | LA | 02/07/1967 | AL | 1712001084 | N | 2 | 5 | |
| | Vehicle Violation: 390 | | | CMV not marked in accordance with regulations | | | oos | | | | | | |
| Vehicle Violation: | | | | • | | | | | | | | | |
| Vehicle Violation: | | | 393.75(a)(3) Tire-fl | at and/or audible air leak | | | | | | | | | |
| Vehicle Violation: | | | 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 NON- | | | | | ION-OOS | | | | | |
| Driver Violation: 395.8(k)(2) Driver | | ailing to retain previous 7 days records of duty status OOS | | | | | | | | | | | |
| Violatio | on Summary | | | | | | | | | | | | |
| Vie | olation # | | | # of Violations | | # of Out-of-service Violations | | | | | | | |
| 396.5(b) |) | Oil and/or gre | ease leak | | | | | | | 1 | | 0 | |
| 393.45 | | Brake tubing | and hose adequacy | | | | | | | 1 | | 1 | |
| 393.75(| a)(3) | Tire-flat and/o | or audible air leak | | 4 | | 2 | | | | | | |

Report executed at: 6/14/2022 9:59:54 AM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

| 390.21T(a) | CMV not marked in accordance with regulations | 1 | 0 |
|-------------|--|---|---|
| 393.95(f) | No / insufficient warning devices | 1 | 0 |
| 393.55(e) | No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998 | 1 | 0 |
| 395.8(k)(2) | Driver failing to retain previous 7 days records of duty status | 1 | 1 |
| 395.22(g) | Portable ELD not mounted in a fixed position and visible to driver | 1 | 0 |

The summary counts and rates only include violations that were attributable to HATHORN, KENNETH.

Report executed at: 6/14/2022 9:59:54 AM

MCMIS snapshot date: 05/27/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.