

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
RODRIGUEZMANUEL	JESUSMANUEL	059111478	GA										
RODRIGUEZJESUS	JESUSMANUEL	059111478	GA										
RODRIGUEZ	JESUS	059111478	GA										
MANUELRODRIGUEZ	JESUSMANUEL	059111478	GA										
MANUELJESUS	JESUSMANUEL	059111478	GA										
MANUEL	JESUSMANUEL	059111478	GA										
JESUSRODRIGUEZ	JESUSMANUEL	059111478	GA										
JESUSMANUEL	JESUSMANUEL	059111478	GA										
JESUS	JESUSMANUEL	059111478	GA										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:		0	# of Crashes with Fatalities:		0	# of Crashes with Injuries:		0	# of Towaways:		0		
# Not preventable:		0	# of Fatalities:		0	# of Injuries:		0	# of Hazmat Releases:		0		
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)														
Inspection Summary														
Driver Summary				Vehicle Summary				Hazmat Summary						
Driver Inspections:				4	Vehicle Inspections:				2	Hazmat Inspections				0
Driver Out-of-service Inspections:				0	Vehicle Out-of-service Inspections:				2	Hazmat Out-of-service Inspections:				0

Report executed at: 7/17/2023 3:06:58 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Driver Out-of-service Rate:				0%	Vehicle Out-of-service Rate:			100%	Hazmat Out-of-service Rate:			0%	
Inspection Details													
Carrier Info				Driver Info					Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	11/30/2020	2941667	KEY CARRIER GROUP CO	RODRIGUEZ, JESUS	059111478	GA	09/06/1980	KY	CV43331437	N	1	1	
Vehicle Violation:		393.9(a)	Inoperative Brake Lamps			OOS							
2	02/07/2021	2941667	KEY CARRIER GROUP CO	RODRIGUEZ, JESUS	059111478	GA	09/06/1980	KY	CV41753057	N	3	1	
Driver Violation:		392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.			NON-OOS							
3	01/14/2023	3071380	FENIX TRANSPORTATION LLC	RODRIGUEZ, JESUS	059111478	GA	09/06/1980	NE	0159000942	N	3	0	
4	05/18/2023	3177874	FREIGHT ONE GROUP INC	RODRIGUEZ, JESUS	059111478	GA	09/06/1980	WI	2654002439	N	1	1	
Vehicle Violation:		393.75(a)(3)	Tire-flat and/or audible air leak			OOS							
Violation Summary													
Violation #		Description							# of Violations		# of Out-of-service Violations		
393.9(a)		Inoperative Brake Lamps							1		1		
393.75(a)(3)		Tire-flat and/or audible air leak							1		1		
392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.							1		0		

The summary counts and rates only include violations that were attributable to RODRIGUEZMANUEL, JESUSMANUEL.

Report executed at: 7/17/2023 3:06:58 PM

MCMIS snapshot date: 06/30/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>