

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
METELUS		ENIEL		M220535514000			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		3		Vehicle Inspections:		3		Hazmat Inspections				0			
Driver Out-of-service Inspections:		2		Vehicle Out-of-service Inspections:		2		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		67%		Vehicle Out-of-service Rate:		67%		Hazmat Out-of-service Rate:				0%			

Report executed at: 5/27/2025 3:00:06 PM

MCMIS snapshot date: 04/25/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/08/2024	4258883	YELLOW AND BLUE 1998 INC	METELUS, ENIEL	M220535514000	FL	02/19/1992	OK	PE13177334	N	1	14
	Vehicle Violation:	393.9A-LSML	LIGHTING - SIDE MARKER LAMP(S) INOPERATIVE			NON-OOS						
	Vehicle Violation:	393.205C-WRAWFLMIB	WHEEL/RIM - ANY WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.			NON-OOS						
	Vehicle Violation:	393.205C-WRAWFLMIB	WHEEL/RIM - ANY WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.			NON-OOS						
	Vehicle Violation:	393.205C-WR	WHEEL/RIM - WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.			OOS						
	Vehicle Violation:	393.205C-WR	WHEEL/RIM - WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.			OOS						
	Vehicle Violation:	393.75A3-TAOLTIS	TIRES - ALL OTHERS, LEAKING IN TREAD AREA AND INFLATION LESS THAN 50% OF THE MAXIMUM INFLATION PRESSURE ON TIRE EQUIPPED WITH ATIS			OOS						
	Vehicle Violation:	393.48A-BIBD	DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE			NON-OOS						
	Vehicle Violation:	393.53B	CMV MANUFACTURED AFTER 10/19/94 HAS AN AUTOMATIC AIRBRAKE ADJUSTMENT SYSTEM THAT FAILS TO COMPENSATE FOR WEAR			NON-OOS						
	Vehicle Violation:	393.47E	BRAKE OUT OF ADJUSTMENT - ROTO, CLAMP (SHORT & LONG), DD-3, OR BOLT			NON-OOS						
	Vehicle Violation:	393.47E	BRAKE OUT OF ADJUSTMENT - ROTO, CLAMP (SHORT & LONG), DD-3, OR BOLT			NON-OOS						
	Vehicle Violation:	396.3A1-BOS	BRAKE - DEFECTIVE BRAKE(S) ARE EQUAL TO OR GREATER THAN 20% OF THE SERVICE BRAKES ON THE VEHICLE/COMBINATION			OOS						
	Vehicle Violation:	392.2-SLLSR	STATE/LOCAL LAWS - STATE REGISTRATION/TAG VIOLATION			NON-OOS						
	Driver Violation:	395.8A1-HOSP	HOS (PROPERTY) - FAILING TO HAVE A RECORD OF DUTY STATUS USING THE METHOD PRESCRIBED			OOS						
	Driver Violation:	392.2-SLLEWA1	STATE/LOCAL LAWS - EXCESSIVE WEIGHT - 1-2500 LBS OVER ON AN AXLE/AXLE GROUPS			NON-OOS						
2	02/05/2025	4258883	YELLOW AND BLUE 1998 INC	METELUS, ENIEL	M220535514000	FL	02/19/1992	MO	1355000629	N	2	11

Report executed at: 5/27/2025 3:00:06 PM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

	Driver Violation:	395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN			NON-OOS						
	Vehicle Violation:	393.60D	WINDSHIELD / WINDOWS - TINTING PERMITS LESS THAN 70% OF LIGHT TRANSMITTANCE			NON-OOS						
	Driver Violation:	395.30B1-ELDDFR	HOS (ELD) - DRIVER FAILING TO REVIEW RECORDS AND CERTIFY THE ACCURACY OF THE INFORMATION.			NON-OOS						
	Driver Violation:	395.24	HOS (ELD) - ELD FORM AND MANNER			NON-OOS						
	Driver Violation:	395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN			NON-OOS						
	Vehicle Violation:	393.55C2-B	AIR BRAKE - CMV OTHER THAN TRUCK-TRACTOR MANUFACTURED ON OR AFTER MARCH 1, 1998 NOT EQUIPPED WITH AN ANTILOCK BRAKE SYSTEM. SYSTEM DOES NOT FUNCTION OR INDICATES			NON-OOS						
	Driver Violation:	392.16-D	DRIVER - FAILED TO USE SEAT BELT WHILE OPERATING A CMV			NON-OOS						
	Driver Violation:	392.60A-D	DRIVER - UNAUTHORIZED PASSENGER(S) ON-BOARD A CMV			NON-OOS						
	Driver Violation:	395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN			NON-OOS						
	Driver Violation:	395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN			NON-OOS						
	Vehicle Violation:	393.11A1-LCL	LIGHTING - CLEARANCE LAMP(S) MISSING			NON-OOS						
3	02/08/2025	4258883	YELLOW AND BLUE 1998 INC	METELUS, ENIEL	M220535514000	FL	02/19/1992	AR	5760000263	N	2	7
	Driver Violation:	392.4A-DOSP	DRUGS/OTHER SUBSTANCES - OPERATE A CMV WHILE IN POSSESSION.			OOS						
	Driver Violation:	395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN			NON-OOS						
	Vehicle Violation:	393.106B-C	CARGO - NOT IMMOBILIZED OR SECURED			NON-OOS						
	Vehicle Violation:	393.207A-SAPPAS	SUSPENSION - AXLE POSITIONING PART CRACKED/BROKEN/LOOSE/MISSING RESULTING IN AXLE SHIFT			OOS						
	Vehicle Violation:	396.3A1-HCM	HUBS - BEARING CAP, PLUG OR FILLER PLUG MISSING OR BROKEN			OOS						
	Vehicle Violation:	393.75A3-TAOL	TIRES - ALL OTHERS, LEAKING OR INFLATION LESS THAN 50% OF THE MAXIMUM INFLATION PRESSURE ON TIRE NOT EQUIPPED WITH ATIS			OOS						
	Vehicle Violation:	393.75A3-TAOL	TIRES - ALL OTHERS, LEAKING OR INFLATION LESS THAN 50% OF THE MAXIMUM INFLATION PRESSURE ON TIRE NOT EQUIPPED WITH ATIS			OOS						
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.9A-LSML		LIGHTING - SIDE MARKER LAMP(S) INOPERATIVE							1			

Report executed at: 5/27/2025 3:00:06 PM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.205C-WRAWFLMIB	WHEEL/RIM - ANY WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.	2	0
393.205C-WVR	WHEEL/RIM - WHEEL FASTENERS LOOSE/MISSING/INEFFECTIVE/BROKEN.	2	2
393.75A3-TAOLTIS	TIRES - ALL OTHERS, LEAKING IN TREAD AREA AND INFLATION LESS THAN 50% OF THE MAXIMUM INFLATION PRESSURE ON TIRE EQUIPPED WITH ATIS	1	1
393.48A-BIBD	DRUM BRAKE - INOPERATIVE OTHER THAN A STEERING AXLE	1	0
393.53B	CMV MANUFACTURED AFTER 10/19/94 HAS AN AUTOMATIC AIRBRAKE ADJUSTMENT SYSTEM THAT FAILS TO COMPENSATE FOR WEAR	1	0
393.47E	BRAKE OUT OF ADJUSTMENT - ROTO, CLAMP (SHORT & LONG), DD-3, OR BOLT	2	0
396.3A1-BOS	BRAKE - DEFECTIVE BRAKE(S) ARE EQUAL TO OR GREATER THAN 20% OF THE SERVICE BRAKES ON THE VEHICLE/COMBINATION	1	1
392.2-SLLSR	STATE/LOCAL LAWS - STATE REGISTRATION/TAG VIOLATION	1	0
395.8A1-HOSP	HOS (PROPERTY) - FAILING TO HAVE A RECORD OF DUTY STATUS USING THE METHOD PRESCRIBED	1	1
392.2-SLLEWA1	STATE/LOCAL LAWS - EXCESSIVE WEIGHT - 1-2500 LBS OVER ON AN AXLE/AXLE GROUPS	1	0
392.4A-DOSP	DRUGS/OTHER SUBSTANCES - OPERATE A CMV WHILE IN POSSESSION.	1	1
395.8E-HOSPD	HOS (PROPERTY) - NO DRIVER MAY MAKE A FALSE REPORT IN CONNECTION WITH A DUTY STATUS. EXPLAIN	5	0
393.106B-C	CARGO - NOT IMMOBILIZED OR SECURED	1	0
393.207A-SAPPAS	SUSPENSION - AXLE POSITIONING PART CRACKED/BROKEN/LOOSE/MISSING RESULTING IN AXLE SHIFT	1	1
396.3A1-HCM	HUBS - BEARING CAP, PLUG OR FILLER PLUG MISSING OR BROKEN	1	1
393.75A3-TAOL	TIRES - ALL OTHERS, LEAKING OR INFLATION LESS THAN 50% OF THE MAXIMUM INFLATION PRESSURE ON TIRE NOT EQUIPPED WITH ATIS	2	2
393.60D	WINDSHIELD / WINDOWS - TINTING PERMITS LESS THAN 70% OF LIGHT TRANSMITTANCE	1	0
395.30B1-ELDDFR	HOS (ELD) - DRIVER FAILING TO REVIEW RECORDS AND CERTIFY THE ACCURACY OF THE INFORMATION.	1	0
395.24	HOS (ELD) - ELD FORM AND MANNER	1	0
393.55C2-B	AIR BRAKE - CMV OTHER THAN TRUCK-TRACTOR MANUFACTURED ON OR AFTER MARCH 1, 1998 NOT EQUIPPED WITH AN ANTILOCK BRAKE SYSTEM. SYSTEM DOES NOT FUNCTION OR INDICATES	1	0
392.16-D	DRIVER - FAILED TO USE SEAT BELT WHILE OPERATING A CMV	1	0
392.60A-D	DRIVER - UNAUTHORIZED PASSENGER(S) ON-BOARD A CMV	1	0
393.11A1-LCL	LIGHTING - CLEARANCE LAMP(S) MISSING	1	0

The summary counts and rates only include violations that were attributable to METELUS, ENIEL.

Report executed at: 5/27/2025 3:00:06 PM

MCMIS snapshot date: 04/25/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>