

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
TORRESSANDOVAL	LUIS	515513167	NM										
SANDOVAL	LUIS ANDRES	515513167	NM										
TORRES	LUIS ANDRES	515513167	NM										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		5		Vehicle Inspections:		3		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%	

Report executed at: 1/11/2022 12:07:43 PM

MCMIS snapshot date: 12/31/2021

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/28/2019	1876301	MAK LOGISTICS LLC	TORRES SANDOVAL, LUIS	515513167	NM	05/06/1966	WA	W422001332	N	2	0
2	07/15/2019	1876301	MAK LOGISTICS LLC	TORRES SANDOVAL, LUIS	515513167	NM	05/06/1966	WA	W418001645	N	2	1
Vehicle Violation:		392.2	Violation of Local Laws - Explain:				NON-OOS					
3	07/17/2019	1876301	MAK LOGISTICS LLC	TORRES SANDOVAL, LUIS	515513167	NM	05/06/1966	WA	W508006139	N	3	0
4	08/08/2019	1876301	MAK LOGISTICS LLC	SANDOVAL, LUIS ANDRES	515513167	NM	05/06/1966	IL	0824860062	N	3	1
Driver Violation:		392.2LV	Lane Restriction violation				NON-OOS					
5	03/07/2020	1876301	MAK LOGISTICS LLC	SANDOVAL, LUIS ANDRES	515513167	NM	05/06/1966	IA	000TT70X9H	N	2	2
Vehicle Violation:		393.9(a)	Inoperable head lamps				NON-OOS					
Driver Violation:		395.8E	False report of drivers record of duty status				NON-OOS					
Violation Summary												
Violation #		Description							# of Violations		# of Out-of-service Violations	
392.2		Violation of Local Laws - Explain:							1		0	
392.2LV		Lane Restriction violation							1		0	
393.9(a)		Inoperable head lamps							1		0	
395.8E		False report of drivers record of duty status							1		0	

The summary counts and rates only include violations that were attributable to TORRESSANDOVAL, LUIS.

Report executed at: 1/11/2022 12:07:43 PM

MCMIS snapshot date: 12/31/2021

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.