

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
PALACIOS		CARLOS		P422108762031			FL								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		4		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		25%		Hazmat Out-of-service Rate:				0%			

Report executed at: 3/25/2025 10:38:19 AM

MCMIS snapshot date: 02/28/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	05/19/2022	3586456	PERFORMANCE HAULING INC	PALACIOS, CARLOS	P422108762031	FL	06/03/1976	MS	6623300604	N	1	6
<div>Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS</div> <div>Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS</div> <div>Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS</div> <div>Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS</div> <div>Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS</div> <div>Vehicle Violation: 396.3(a)(1) Brake system pressure loss OOS</div>												
2	12/14/2023	3927679	AMERICAN AUTO LOGISTICS LLC	PALACIOS, CARLOS	P422108762031	FL	06/03/1976	NM	4396N9OB4Q	N	2	0
3	07/04/2024	3425544	PRESTIGE MAINTENANCE OF S F CORP	PALACIOS, CARLOS	P422108762031	FL	06/03/1976	FL	3857003445	N	2	0
<div>Vehicle Violation: 393.95(a)(1) Emergency Equipment - Fire Extinguishers - no fire extinguisher present or not properly rated. NON-OOS</div> <div>Vehicle Violation: 393.11(b) Conspicuity Systems - Trailers, side retro reflective sheeting inadequate on vehicle manufactured on or after December 1, 1993 NON-OOS</div>												

Report executed at: 3/25/2025 10:38:19 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

4	07/16/2024	3425544	PRESTIGE MAINTENANCE OF S F CORP	PALACIOS, CARLOS	P422108762031	FL	06/03/1976	FL	3253008376	N	2	0
Driver Violation:	392.2	State/Local Laws - Excessive Weight Violations				NON-OOS						
Vehicle Violation:	393.11(b)	Conspicuity Systems - Trailers, side retro reflective sheeting inadequate on vehicle manufactured on or after December 1, 1993				NON-OOS						
Vehicle Violation:	393.11(b)	Conspicuity Systems - Trailers, rear impact guard retro reflective sheeting inadequate on vehicle manufactured on or after December 1, 1993				NON-OOS						
Vehicle Violation:	396.17(c)	Operating a CMV without documentation of a periodic inspection				NON-OOS						
Vehicle Violation:	393.78(a)	Washers - Inoperative washing system.				NON-OOS						
Vehicle Violation:	396.17(c)	Operating a CMV without documentation of a periodic inspection				NON-OOS						
Vehicle Violation:	393.11(a)(1)	Conspicuity Systems - Truck tractor, lower rear retro reflective sheeting missing on vehicle manufactured on or after July 1, 1997				NON-OOS						
Vehicle Violation:	393.95(a)(4)	Emergency Equipment - Fire Extinguishers - unsecured				NON-OOS						
Vehicle Violation:	393.95(a)(1)	Emergency Equipment - Fire Extinguishers - no fire extinguisher present or not properly rated.				NON-OOS						

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
393.95(a)(1)	Emergency Equipment - Fire Extinguishers - no fire extinguisher present or not properly rated.	2	0
393.11(b)	Conspicuity Systems - Trailers, side retro reflective sheeting inadequate on vehicle manufactured on or after December 1, 1993	3	0
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt	3	0
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	2	2
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	1	0
392.2	State/Local Laws - Excessive Weight Violations	1	0
396.17(c)	Operating a CMV without documentation of a periodic inspection	2	0
393.78(a)	Washers - Inoperative washing system.	1	0
393.11(a)(1)	Conspicuity Systems - Truck tractor, lower rear retro reflective sheeting missing on vehicle manufactured on or after July 1, 1997	1	0
393.95(a)(4)	Emergency Equipment - Fire Extinguishers - unsecured	1	0

The summary counts and rates only include violations that were attributable to PALACIOS, CARLOS.

Report executed at: 3/25/2025 10:38:19 AM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>