

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
ZAMORACABALLERO	ARGELIO	Z562000760610	FL										
ZAMORA	ARGELIO	Z562000760610	FL										
CABALLERO	ARGELIO	Z562000760610	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries		
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:	4			Vehicle Inspections:	2			Hazmat Inspections:	0				
Driver Out-of-service Inspections:	1			Vehicle Out-of-service Inspections:	1			Hazmat Out-of-service Inspections:	0				
Driver Out-of-service Rate:	25%			Vehicle Out-of-service Rate:	50%			Hazmat Out-of-service Rate:	0%				

Report executed at: 7/1/2024 11:03:02 AM

MCMIS snapshot date: 05/31/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	12/08/2021	2337729	HUGO R RODRIGUEZ	ZAMORA, ARGELIO	Z562000760610	FL	02/21/1976	TX	66KK0XIXPO	N	3	3
Vehicle Violation:		396.17(c)	Operating a CMV without proof of a periodic inspection			NON-OOS						
Vehicle Violation:		396.17(c)	Operating a CMV without proof of a periodic inspection			NON-OOS						
Driver Violation:		383.23(a)(2)	Operating a CMV without a CDL			OOS						
2	11/24/2022	3752942	ANDOBAL LOGISTIC LLC	ZAMORA CABALLERO, ARGELIO	Z562000760610	FL	02/21/1976	OH	1251009383	N	2	4
Vehicle Violation:		387.301(a)	Carrier -Motor carrier shall not engage in interstate or foreign commerce without proof of public liability and property damage insurance as required in 49 CFR 38			NON-OOS						
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperable Required Lamp			NON-OOS						
Vehicle Violation:		396.3(a)(1)	Brake system pressure loss			NON-OOS						
3	04/06/2023	2316314	DVS TRANSPORTATION INC	ZAMORA CABALLERO, ARGELIO	Z562000760610	FL	02/21/1976	OH	3280009171	N	3	0
4	08/18/2023	2316314	DVS TRANSPORTATION INC	ZAMORA CABALLERO, ARGELIO	Z562000760610	FL	02/21/1976	IN	3909005155	N	2	4
Vehicle Violation:		393.45	Brake Tubing and Hose Adequacy - Connections to Power Unit			OOS						
Vehicle Violation:		393.45	Brake Tubing and Hose Adequacy - Connections to Power Unit			NON-OOS						
Vehicle Violation:		393.9(a)	Inoperative turn signal			OOS						
Vehicle Violation:		393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001			NON-OOS						
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.17(c)	Operating a CMV without proof of a periodic inspection								2	0		
383.23(a)(2)	Operating a CMV without a CDL								1	1		
393.45	Brake Tubing and Hose Adequacy - Connections to Power Unit								2	1		
393.9(a)	Inoperative turn signal								2	1		
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001								1	0		
387.301(a)	Carrier -Motor carrier shall not engage in interstate or foreign commerce without proof of public liability and property damage insurance as required in 49 CFR 38								1	0		

Report executed at: 7/1/2024 11:03:02 AM

MCMIS snapshot date: 05/31/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
396.3(a)(1)	Brake system pressure loss	1	0

The summary counts and rates only include violations that were attributable to ZAMORACABALLERO, ARGELIO.

Report executed at: 7/1/2024 11:03:02 AM

MCMIS snapshot date: 05/31/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.