

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
MOZODEBROK	YUSEL	44930430	TX										
MOZO	YUSEL	44930430	TX										
DEBROK	YUSEL	44930430	TX										

Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	

Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0	
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%	

Report executed at: 8/21/2024 3:42:22 PM

MCMIS snapshot date: 07/26/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	10/08/2022	776063	AMIGOS MEAT DISTRIBUTORS LP	MOZO DEBROK, YUSEL	44930430	TX	06/03/1981	TX	6F089DCCCR	N	2	8
<div>Vehicle Violation: 396.3(a)(1) BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination OOS</div> <div>Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS</div> <div>Vehicle Violation: 393.47(e) Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt NON-OOS</div> <div>Vehicle Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear NON-OOS</div> <div>Vehicle Violation: 393.51 No or defective brake warning device or pressure gauge NON-OOS</div> <div>Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS</div> <div>Vehicle Violation: 393.30 Improper battery installation NON-OOS</div> <div>Vehicle Violation: 393.11 No or defective lighting devices or reflective material as required NON-OOS</div>												
2	12/30/2022	265752	FEDEX GROUND PACKAGE SYSTEM INC	MOZO DEBROK, YUSEL	44930430	TX	06/03/1981	NM	5061MA4C95	N	2	0
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
396.3(a)(1)	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination								1	1		
393.47(e)	Brake Out of Adjustment - Roto, Clamp (Short & Long), DD-3, or Bolt								2	0		
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear								1	0		
393.51	No or defective brake warning device or pressure gauge								1	0		
393.9(a)	Inoperable Required Lamp								1	0		
393.30	Improper battery installation								1	0		
393.11	No or defective lighting devices or reflective material as required								1	0		

The summary counts and rates only include violations that were attributable to MOZODEBROK, YUSEL.

Report executed at: 8/21/2024 3:42:22 PM

MCMIS snapshot date: 07/26/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>