

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #			State								
SOTO		REINALDO		43899489			TX								
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		2		Vehicle Inspections:		2		Hazmat Inspections				0			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		1		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		50%		Hazmat Out-of-service Rate:				0%			

Report executed at: 7/16/2024 3:05:24 PM

MCMIS snapshot date: 06/28/2024

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	11/28/2021	2471086	INTERFLET TRANSPORT INC	SOTO HERNANDEZ, REINALDO	43899489	TX	11/02/1966	TX	66A90VKOAY	N	2	5
Vehicle Violation: 393.78 Wipers - Inoperative / missing / damaged wipers. NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.45(d) Brake Connections with Leaks Under Vehicle NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal OOS												
2	11/08/2022	2471086	INTERFLET TRANSPORT INC	SOTO, REINALDO	43899489	TX	11/02/1966	SC	R367000261	N	2	1
Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS												
Violation Summary												
Violation #	Description								# of Violations	# of Out-of-service Violations		
393.78	Wipers - Inoperative / missing / damaged wipers.								1	0		
393.9(a)	Inoperable Required Lamp								4	1		
393.45(d)	Brake Connections with Leaks Under Vehicle								1	0		

The summary counts and rates only include violations that were attributable to SOTO, REINALDO.

Report executed at: 7/16/2024 3:05:24 PM

MCMIS snapshot date: 06/28/2024

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>