

# PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information															
Last Name		First Name		License #				State							
JOHNSON		RONALD		26833996				TX							
Crash Activity															
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
# of Crashes:		0		# of Crashes with Fatalities:		0		# of Crashes with Injuries:		0		# of Towaways:		0	
# Not preventable:		0		# of Fatalities:		0		# of Injuries:		0		# of Hazmat Releases:		0	
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)															
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries			
Inspection Activity (3 year history from MCMIS snapshot date)															
Inspection Summary															
Driver Summary				Vehicle Summary				Hazmat Summary							
Driver Inspections:		4		Vehicle Inspections:		3		Hazmat Inspections				2			
Driver Out-of-service Inspections:		0		Vehicle Out-of-service Inspections:		0		Hazmat Out-of-service Inspections:				0			
Driver Out-of-service Rate:		0%		Vehicle Out-of-service Rate:		0%		Hazmat Out-of-service Rate:				0%			
Inspection Details															
Carrier Info				Driver Info				Inspection Info							
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol			
1	03/06/2023	281216	L & B TRANSPORT LLC	JOHNSON, RONALD	26833996	TX	11/04/1988	TX	6J560XSLQC	Y	2	1			
Vehicle Violation:		393.209(d)		Steering system components worn, welded, or missing				NON-OOS							

Report executed at: 2/13/2025 2:57:15 PM

MCMIS snapshot date: 01/31/2025

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

2	03/09/2024	184668	GRAMMER LOGISTICS	JOHNSON, RONALD	26833996	TX	11/04/1988	TX	6TEJ9DCCKC	Y	2	2
Vehicle Violation:		393.95(f)	Emergency Equipment - Stopped vehicle warning devices missing or improper			NON-OOS						
Vehicle Violation:		392.2	State vehicle registration or License Plate violation			NON-OOS						
3	03/31/2024	184668	GRAMMER LOGISTICS INC	JOHNSON, RONALD	26833996	TX	11/04/1988	VA	6720000055	N	2	0
4	09/09/2024	3489728	BG LOGISTICS INC	JOHNSON, RONALD	26833996	TX	11/04/1988	SD	1620000516	N	3	0
<b>Violation Summary</b>												
Violation #		Description							# of Violations		# of Out-of-service Violations	
393.209(d)		Steering system components worn, welded, or missing							1		0	
393.95(f)		Emergency Equipment - Stopped vehicle warning devices missing or improper							1		0	
392.2		State vehicle registration or License Plate violation							1		0	

The summary counts and rates only include violations that were attributable to JOHNSON, RONALD.

Report executed at: 2/13/2025 2:57:15 PM

MCMIS snapshot date: 01/31/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>