

PSP Detailed Report

Federal Motor Carrier Safety Administration

Driver Information													
Last Name	First Name	License #	State										
ISRAELADIR	GAVRIEL ADIR	I264281862960	FL										
ISRAEL	GAVRIEL	I264281862960	FL										
ADIRISRAEL	GAVRIEL ADIR	I264281862960	FL										
ADIR	GAVRIEL ADIR	I264281862960	FL										
Crash Activity													
Crash Summary (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
# of Crashes:	0	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	0	# of Towaways:	0						
# Not preventable:	0	# of Fatalities:	0	# of Injuries:	0	# of Hazmat Releases:	0						
Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)													
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Location	# Fatalities	# of Injuries	
Inspection Activity (3 year history from MCMIS snapshot date)													
Inspection Summary													
Driver Summary				Vehicle Summary				Hazmat Summary					
Driver Inspections:	11			Vehicle Inspections:	9			Hazmat Inspections				0	
Driver Out-of-service Inspections:	1			Vehicle Out-of-service Inspections:	6			Hazmat Out-of-service Inspections:				0	
Driver Out-of-service Rate:	9%			Vehicle Out-of-service Rate:	67%			Hazmat Out-of-service Rate:				0%	

Report executed at: 2/10/2023 10:11:16 AM

MCMIS snapshot date: 01/27/2023

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Inspection Details												
Carrier Info				Driver Info				Inspection Info				
	Date	DOT #	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol
1	06/16/2020	316378	BONUS TRANSPORTATION INC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	FL	3164013060	N	2	6
Vehicle Violation: 396.3(a)(1) Brake system pressure loss OOS Vehicle Violation: 393.9(a) Inoperative Brake Lamps OOS Vehicle Violation: 393.9(a) Inoperative Brake Lamps NON-OOS Vehicle Violation: 393.9(a) Inoperable tail lamp NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS Vehicle Violation: 393.9(a) Inoperative turn signal NON-OOS												
2	11/11/2020	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	CA	ND7U002892	N	1	2
Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS Vehicle Violation: 393.45 Brake tubing and hose adequacy OOS												
3	11/11/2020	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	CA	ND74002796	N	1	0
4	11/25/2020	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	CA	ND0G001312	N	2	2
Vehicle Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups. NON-OOS Vehicle Violation: 393.75(a)(3) Tire-flat and/or audible air leak OOS												
5	12/18/2020	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	OH	1367000623	N	1	6
Driver Violation: 392.2 State/Local Laws - Speeding 6-10 miles per hour over the speed limit. NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.9(a) Inoperable Required Lamp NON-OOS Vehicle Violation: 393.45 Brake Tubing and Hose Adequacy - Connections to Power Unit NON-OOS												

Report executed at: 2/10/2023 10:11:16 AM

MCMIS snapshot date: 01/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

6	01/07/2021	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	LA	LAGR002684	N	3	2
Driver Violation:		392.22(b)	Failure to place or improper placement of warning devices on the road surface		NON-OOS							
Driver Violation:		392.22(a)	Failing to use hazard warning flashers		NON-OOS							
7	03/10/2021	2540798	MERCATOR GLOBAL LOGISTICS LLC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	UT	21JJ000161	N	1	8
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS							
Driver Violation:		383.51(a)	Driving a CMV while CDL is suspended for a non-safety-related reason and outside the state of driver's license issuance.		OOS							
Vehicle Violation:		393.9(a)	Inoperable Required Lamp		NON-OOS							
Vehicle Violation:		393.9(a)	Inoperable tail lamp		NON-OOS							
Vehicle Violation:		396.3(a)(1)	Brake system pressure loss		NON-OOS							
Vehicle Violation:		393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998		NON-OOS							
Vehicle Violation:		393.75(h)	Under inflated tire		OOS							
Vehicle Violation:		393.95(a)	No/discharged/unsecured fire extinguisher		NON-OOS							
8	08/12/2021	2440672	KEEN CARGO INC	ISRAEL, GAVRIEL (co-driver)	I264281862960	FL	08/16/1986	GA	1304002450	N	3	8
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Driver Violation:		395.8	Record of Duty Status violation (general/form and manner)		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
Vehicle Violation:		396.17(c)	Operating a CMV without proof of a periodic inspection		NON-OOS	- This violation does NOT apply to ISRAEL, GAVRIEL.						
9	10/06/2021	2440672	KEEN CARGO INC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	CA	NBFL002858	N	1	6
Vehicle Violation:		393.60(e)	Windshield - Obstructed		NON-OOS							
Vehicle Violation:		393.45	Brake tubing and hose adequacy		OOS							
Vehicle Violation:		392.2	State vehicle registration or License Plate violation		NON-OOS							
Vehicle Violation:		396.3(a)(1)	Brakes (general) Explain:		NON-OOS							
Vehicle Violation:		393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove		NON-OOS							
Vehicle Violation:		392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on allowable gross weight.		NON-OOS							
10	02/07/2022	2440672	KEEN CARGO INC	ISRAEL, GAVRIEL	I264281862960	FL	08/16/1986	IN	9512003026	N	1	1

Report executed at: 2/10/2023 10:11:16 AM

MCMIS snapshot date: 01/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Vehicle Violation:		393.9(a)		Inoperable Required Lamp		NON-OOS							
11	06/28/2022	2440672	KEEN CARGO INC	GAVRIEL, ISRAEL		I264281862960	FL	08/16/1986	TN	TFCO001035	N	2	1
Vehicle Violation:		393.75(c)		Tire-other tread depth less than 1/32 of inch measured in 2 adjacent major tread grooves 3 separate locations 8 inches apart				OOS					
Violation Summary													
Violation #		Description								# of Violations		# of Out-of-service Violations	
393.75(a)(3)		Tire-flat and/or audible air leak								2		2	
393.45		Brake tubing and hose adequacy								3		2	
396.3(a)(1)		Brake system pressure loss								3		1	
393.9(a)		Inoperative Brake Lamps								12		1	
392.2		State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.								4		0	
392.22(b)		Failure to place or improper placement of warning devices on the road surface								1		0	
392.22(a)		Failing to use hazard warning flashers								1		0	
395.8		Record of Duty Status violation (general/form and manner)								1		0	
383.51(a)		Driving a CMV while CDL is suspended for a non-safety-related reason and outside the state of driver's license issuance.								1		1	
393.55(e)		No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998								1		0	
393.75(h)		Under inflated tire								1		1	
393.95(a)		No/discharged/unsecured fire extinguisher								1		0	
393.60(e)		Windshield - Obstructed								1		0	
393.75(c)		Tire-other tread depth less than 2/32 of inch measured in a major tread groove								2		1	

The summary counts and rates only include violations that were attributable to ISRAELADIR, GAVRIEL ADIR.

Report executed at: 2/10/2023 10:11:16 AM

MCMIS snapshot date: 01/27/2023

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

For an explanation of FMCSA-reportable crashes see: <https://www.psp.fmcsa.dot.gov/psp/?redirectUrl=FAQ>