

# DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

**California Highway Patrol**  
**5951 Hwy 58**  
**Mojave, CA 93501**  
**Phone: (661) 824-2496**  
**Internationally Accredited Agency CHP407F/343A**

**Report Number:** CANC0Q002034  
**Inspection Date:** 07/25/2022  
**Start:** 6:53 AM PT **End:** 07:46 AM PT  
**Inspection Level:** I - Full  
**HM Inspection Type:** None

**NTT TRANSPORT LLC**  
**55 SE 6TH ST APT 1803**  
**MIAMI, FL 33131**  
**USDOT#:** 03767161 **Phone#:** (786)399-1190  
**MC/MX#:** 00000000 **Fax#:**  
**State#:**

**Driver:** GUZMAN, EDUARDO  
**License#:** G255200701490 **State:** FL  
**Date of Birth:** 04/29/1970  
**CoDriver:**  
**License#:** **State:**  
**Date of Birth:**

**Location:** CACHE CREEK SCALES **MilePost:** 106.00 **Shipper:** NATIONAL GYPSUM  
**Highway:** SR-58 **Origin:** PRYOR,OK **Bill of Lading:** 819836  
**County:** **Destination:** RICHMOND,CA **Cargo:** COMMODITIES, DRY BULK

## VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	New CVSA #	OOS#
1	TT	VOLV	2016	FL	JE64CV	2525/RED	4V4NC9EH8GN942525	53,000		31558306	
2	ST	WANC	2005	FL	QA70IC	054/VAN	1JJV532W75L903074	65,000			

## BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	N/A	N/A	N/A	1 1/2	1 1/2
Left	N/A	N/A	N/A	1 1/2	INOP
Chamber	DISC	DISC	DISC	L-30	L-30

## VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.2DIM	35400(A) CVC/002	2	N		N	N	Multi-axle, semitrailer over 48 feet in length does not have a kingpin to rear axle (KPRA) measurement of 40 feet or less--392.2DIM--Specify: 53' trailer with a 46' KPRA
392.2-SLLEWG1	35551(A) CVC/001	1	N		N	N	Overweight axle groups (1-2500 lbs. over)--392.2-SLLEWG1--Specify: x2x3 Overweight 35,100lbs ( 34,000lbs allowed )
396.3A1BOS	1239 T-13 CCR/055	2	Y		A	N	<b>Brakes out of Service: The number of defective brakes is equal to or greater than 20% of the service brakes on the vehicle(s) OOS violation--396.3A1BOS--Specif</b>
393.47A	26453 CVC/024	2	N		N	N	Other defective lining conditions--393.47A--Specify: x4 L/ x5 L/ contaminated brake linings -20%
393.48A	26453 CVC/004	2	N		N	N	Inoperative brake-If OOS use 1239 T-13 CCR--393.48A--Specify: x5 L/-20%
396.3A1	1232(A) T-13 CC R/036	2	N		N	N	Hubs, oil and/or grease leaking from inner wheel-If OOS use 1239 T-13 CCR--396.3A1--Specify: x5 R/ inner wheel seal leaking ( no brake contamination )
393.45	1239 T-13 CCR/085	2	Y		A	N	<b>Air brake hose or tubing has damage through the reinforcement ply OOS violation--393.45--Specify: x5 R/ emergency air hose leading to brake chamber cut through the cords @hose clamp under air reservoir</b>
396.3A1	1232(A) T-13 CC	2	N		N	N	Motor carrier fail to ensure general

**Report Prepared By:**  
C. RATLIFF

**Badge #:**  
A15578

**Copy Received By:**  
EDUARDO GUZMAN

Page 1 of 2



03767161 CA CANC0Q002034

X\_\_\_\_\_

X\_\_\_\_\_

# DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

**California Highway Patrol**  
**5951 Hwy 58**  
**Mojave, CA 93501**  
**Phone: (661) 824-2496**  
**Internationally Accredited Agency CHP407F/343A**

**Report Number:** CANC0Q002034  
**Inspection Date:** 07/25/2022  
**Start:** 6:53 AM PT **End:** 07:46 AM PT  
**Inspection Level:** I - Full  
**HM Inspection Type:** None

**NTT TRANSPORT LLC**  
**55 SE 6TH ST APT 1803**  
**MIAMI, FL 33131**  
**USDOT#:** 03767161  
**MC/MX#:** 00000000  
**State#:**

**Phone#:** (786)399-1190  
**Fax#:**

**Driver:** GUZMAN, EDUARDO  
**License#:** G255200701490 **State:** FL  
**Date of Birth:** 04/29/1970  
**CoDriver:**  
**License#:** **State:**  
**Date of Birth:**

<u>Vio Code</u>	<u>Section</u> R/001	<u>Unit</u>	<u>OOS</u>	<u>Citation #</u>	<u>Verify</u>	<u>Crash</u>	<u>Violations Discovered</u>
396.5B-HWSLIW	1239 T-13 CCR/3 21	2	Y	CW291356	A	N	maintenance of vehicle--396.3A1--Specify: x4x5 Air tank loose @ mounts <b>Hubs, oil and/or grease leaking from inner            wheel seal, brake friction material            contaminated, evidence that further leaking            will occur OOS violation--396.5B-HWSL: x4 L/            x5 L/ inner wheel seal leaking fluid with brake            contamination</b>

**HazMat:** No HM Transported.

**Placard:** No **Cargo Tank:**

**Special Checks:** Size & Weight;

## State Information:

Beat/Sub Area: 880; Cit-1: CW291356; Officer ID1: 18700; Pre-Cleared Vehicle: N; Regulated Vehicle: Y; Type1: 281; Veh #1 Type: 25; Veh #2 Type: 40;

I hereby declare each vehicle with a Y in the OOS column of the violation section of this report to be OUT-OF-SERVICE. No person shall operate such vehicle until all OUT-OF-SERVICE defects have been repaired and the vehicle has been restored to safe operating condition.

This copy of the report is for your information. Carriers are required to take corrective actions for all defects noted prior to redispach . DO NOT return this form to the California Highway Patrol. NOTE: If a citation was issued, you MUST follow the instructions listed on the citation.

Signature Of Motor Carrier X: \_\_\_\_\_ Title: \_\_\_\_\_ Date: \_\_\_\_\_

**Report Prepared By:**  
**C. RATLIFF**

**Badge #:**  
**A15578**

**Copy Received By:**  
**EDUARDO GUZMAN**

Page 2 of 2



03767161 CA CANC0Q002034

X \_\_\_\_\_

X \_\_\_\_\_