PSP Detailed Report

Federal Motor Carrier Safety Administration

						Driv	er Inf	orm	nation									
Last	Name			First Name			Lice	nse #	#				State					
MEN	IDOZA			JAIME			291	84600	0				TX					
MENDOZA JAIME EUGENIO							M532425584510						FL					
						Cr	rash /	Activ	vity									
Cra	sh Summary	(Crashes liste	d represent a	driver's involv	/ement	t in FMCSA-reportable	crash	nes, v	without ar	ny dete	rmination as	to resp	onsibil	ity.)				
# of Crashes: 1 # of Crashes with Fatalities: 0 #						# of Crash	es with li	njuries:	1		# of Tov	vaways:	1					
# Not preventable: 0 # of Fatalities: 0 # of Injuries: 1 # of Hazmat Rele							eleases:	leases: 0										
Cra	Crash Details (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility.)																	
	Date	Date DOT # Carrier Name		er Name		Driver Name		Driver Lic			tate Driver DOB Rpt St			Number	er Location # Fatalities		# of Injuries	
1	10/11/2023	0/11/2023 1149281 JUGNU TRUCKING LLC MENDOZA, JAIME 29184600 TX				12/11/1958	KS	KS2023E26668 K254 0			0	1						
				li	nspect	tion Activity (3 year	histo	ory f	from MCN	/IIS sn	apshot date	e)						
Insp	ection Sumr	nary																
		Driver :	Summary			\	/ehicle	Sum	nmary					Н	azmat Summa	ry		
Driv	er Inspections				9 \	Vehicle Inspections:				5 H a	5 Hazmat Inspections					0		
Driv	er Out-of-servi	ce Inspections:			1 \	Vehicle Out-of-service Inspections:					1 H a	Hazmat Out-of-service Inspections:					0	
Driv	er Out-of-servi	ce Rate:			11% \	Vehicle Out-of-service Ra	ite:				20% H a	azmat Oı	ıt-of-ser	vice Rate	:			0%

Report executed at: 3/26/2025 3:44:31 PM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Carrie	r Info			Driver Info				Inspection Info					
	Date	DOT#	Carrier Name	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Level	# of Viol	
1	03/17/2022	3170124	R A BAXLEY TRANSPORTATION	MENDOZA, JAIME	29184600	TX	12/11/1958	МО	W239006025	N	1	2	
	Vehicle \	/iolation:	393.75(g) Weigl	nt carried exceeds tire load limit		(oos						
	Driver Violation: 395.8(a)(1) ELD -		No record of duty status (ELD Required) OOS										
2	07/12/2023	1149281	JUGNU TRUCKING LLC	MENDOZA, JAIME	29184600	TX	12/11/1958	МО	W096001624	N	2	3	
	Vehicle \	/iolation:		other tread depth less than 2/32 of inch measured in a major NON-OOS groove									
	Driver Violation: 395.24(c)(2)(iii) Drive		r failed to manually add shipping document number			NON-OOS							
	Driver Violation: 395.24(c)(2)(ii) Drive		r failed to manually add the trailer number			NON-OOS							
3	08/16/2023	1149281	PARAMJIT SINGH	MENDOZA, JAIME	29184600	TX	12/11/1958	TX	V231082646	N	2	0	
4	11/15/2023	1149281	JUGNU TRUCKING LLC	MENDOZA, JAIME	29184600	TX	12/11/1958	TN	MDBR000849	N	3	1	
	Driver Vi	olation:	395.24(d) ELD (cannot transfer ELD records electronically		NON-0	oos						
5	12/19/2023	1149281	PARAMJIT SINGH	MENDOZA, JAIME	29184600	TX	12/11/1958	KY	CV41882682	N	3	1	
	Driver Vi	olation:	392.2 Unlay	vfully parking and/or leaving vehicle in the ro	padway	NON-0	oos						
6	03/29/2024	1437731	STAR TRANSPORTATION PA INC	MENDOZA, JAIME	29184600	TX	12/11/1958	ОН	0486000296	N	3	1	
	Driver Vi	olation:	392.2 State, limit	Local Laws - Speeding 11-14 miles per hou	r over the speed	NON-0	oos						
		1437731	STAR TRANSPORTATION	MENDOZA, JAIME	29184600	TX	12/11/1958	MD	3271000985	N	2	0	
7	04/08/2024	1407701	PA INC										
7	04/08/2024	1407701	PA INC										

Report executed at: 3/26/2025 3:44:31 PM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

9	08/11/2024	2450913	REAL TRANSPORT COR	P MENDOZA, JAIME	29184600	TX	12/11/1958	TX	V241497636	N	2	4
	Vehicle Violation: 393.78		393.78 Wij	Wipers - Inoperative / missing / damaged wipers			oos					
	Vehicle Violation:			or Defective ABS Malfunction Indicator Lamp f nufactured after 03/01/1998	or trailer	NON-C	oos					
	Vehicle Violation:		393.11 No	or defective lighting devices or reflective mater	rial as required	NON-C	oos					
Vehicle Violation:			ck-Tractor lower rear mud flaps retroreflective ective material requirements for vehicles manu 97		NON-C	oos						

Violation Summary

Violation #	Description	# of Violations	# of Out-of-service Violations
395.24(d)	ELD cannot transfer ELD records electronically	1	0
393.78	Wipers - Inoperative / missing / damaged wipers	1	0
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	1	0
393.11	No or defective lighting devices or reflective material as required	2	0
392.2	State/Local Laws - Speeding 11-14 miles per hour over the speed limit	2	0
393.75(c)	Tire-other tread depth less than 2/32 of inch measured in a major tread groove	1	0
395.24(c)(2)(iii)	Driver failed to manually add shipping document number	1	0
395.24(c)(2)(ii)	Driver failed to manually add the trailer number	1	0
393.75(g)	Weight carried exceeds tire load limit	1	1
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1

The summary counts and rates only include violations that were attributable to MENDOZA, JAIME.

Report executed at: 3/26/2025 3:44:31 PM

MCMIS snapshot date: 02/28/2025

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.