## **PSP** Detailed Report

Federal Motor Carrier Safety Administration

Driver Information														
Last Name	First Name	License #				State								
RIOS	ISABELINO	F4346735				CA								
RIOS	ISABELINO JAUSTIN	СН	F4346735					CA						
CHARVEZRIOS	ISABELINO JAUSTIN	СН	F434	F4346735					CA					
AUSTINCHARVEZRIOS	ISABELINO JAUSTIN CH			F4346735					CA					
CHARVEZAUSTIN	ISABELINO JAUSTIN CH			F4346735				CA						
RIOSAUSTIN	ISABELINO JAUSTIN CH			F4346735					СА					
AUSTIN	ISABELINO JAUSTIN CH			F4346735					CA					
AUSTINCHARVEZ	ISABELINO JAUSTIN CH			F4346735					СА					
AUSTINRIOS	ISABELINO JAUSTIN CH			F4346735				CA						
RIOSCHARVEZ	ISABELINO JAUSTIN CH			F4346735				CA						
RIOSAUSTINCHARVEZ	ISABELINO JAUSTIN CH			F4346735				CA						
	•	Cr	ash A	Activ	ity									
Crash Summary (Crashes listed represent a	a driver's involveme	nt in FMCSA-reportable	crash	nes, w	vithout a	ny dete	rmination as	s to resp	onsibil	ity.)				
# of Crashes:	0	# of Crashes with Fata	lities:	0	# of Crashes with			nes with Ir	njuries: 0 # of T			# of To	waways:	0
# Not preventable:	0	# of Fata	lities:	0		# of I			njuries:	0	# of Hazmat Releases:			0
Crash Details (Crashes listed represent a d	river's involvement i	in FMCSA-reportable cr	ashes,	, with	out any	determ	ination as to	o respon	sibility	.)				
Date DOT # Carrier Name Driver Name		Driver Name	D	Driver	Lic State Driver DOB Rpt St			Report	Number	Location	# Fatalities	# Inju	ries	
Inspection Activity (3 year history from MCMIS snapshot date)														
Inspection Summary														
Driver Summary		N N	/ehicle	Sumn	nary					ŀ	lazmat Summa	ary		

Report executed at: 5/20/2022 9:49:02 AM

MCMIS snapshot date: 04/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

Driver Inspections:				6	6 Vehicle Inspections:			4 Hazmat Ir	Hazmat Inspections				0
Driver Out-of-service Inspections:			1	Vehicle Out-of-service Inspectio		1 Hazmat C	Hazmat Out-of-service Inspections:				0		
Driver Out-of-service Rate:			17%	% Vehicle Out-of-service Rate:			25% Hazmat C	Hazmat Out-of-service Rate:				0%	
Inspec	tion Details												
Carrie	er Info Driver Info Inspe							Inspec	spection Info				
	Date	DOT #	Carrier Na	ame	Driver Name	Driver Lic	State	Driver DOB	Rpt St	Report Number	Hazmat Insp	Insp Leve	el # of Viol
1	09/18/2019	3291996	SUPREME TRA	NSS LLC RIOS,	ISABELINO	F4346735	CA	08/23/1988	со	PF29501008	N	2	0
2	09/23/2019	3003564	PUGET TRANSP	PORT LLC RIOS,	ISABELINO	F4346735	CA	08/23/1988	WA	W727000116	N	2	1
	Vehicle \	/ehicle Violation: 392.9(a) Failing to secure load OOS											
3	03/05/2020	1873056	YARB TRANSPC	ORTATION RIOS,	ISABELINO	F4346735	CA	08/23/1988	ТХ	50PE9DIR2M	N	2	5
	Vehicle \	/iolation:										_	-
	Vehicle \	/iolation:											
	Vehicle	le Violation: 393.9(a) Inoperable Required Lamp NON-OOS											
	Vehicle	Phicle Violation: 393.78 Windshield wipers inoperative/defective NON-OOS											
	Vehicle V	/iolation:	396.5(b)	) Oil and/or grease leak NON-OOS									
4	06/20/2020	2400897	UNION CARRI	ERS LLC RIOS,	RIOS, ISABELINO F4346735 CA 08/23/198				WA	B204000269	N	2	1
	Driver Vi	olation:	ation: 395.8(a)(1) ELD - No record of duty status (ELD Required) OOS										
5	06/30/2020	2400897	UNION CARRI	ERS LLC RIOS,	ISABELINO	F4346735	CA	08/23/1988	CA	UBXK000886	N	3	1
	Vehicle V	Violation: 392.2 State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups. NON-OOS									-		
6	07/09/2020	2400897	UNION CARRI	ERS LLC RIOS,	ISABELINO	F4346735	CA	08/23/1988	WA	W109008795	N	3	3
	Driver Vi	Violation: 395.24(d) ELD cannot transfer ELD records electronically NON-OOS								-			
	Vehicle Violation:392.2IRP Apportioned Tag or Registration ViolationNON-OOS												
	Driver Vi	olation:	392.2	Failure to obe	ey traffic control device		NON-C	OOS					
Violati	on Summary												
Vi	Violation #			Description					# of Violati	# of Violations			
392.2R	3	State vehicle	registration or Licer	nse Plate violation							1		0

Report executed at: 5/20/2022 9:49:02 AM

MCMIS snapshot date: 04/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

393.9(a)	Inoperable head lamps	2	0
393.78	Windshield wipers inoperative/defective	1	0
396.5(b)	Oil and/or grease leak	1	0
395.8(a)(1)	ELD - No record of duty status (ELD Required)	1	1
392.9(a)	Failing to secure load	1	1
392.2	State/Local Laws - Excessive weight - 1-2500 lbs over on an axle/axle groups.	3	0
395.24(d)	ELD cannot transfer ELD records electronically	1	0

The summary counts and rates only include violations that were attributable to RIOS, ISABELINO.

Report executed at: 5/20/2022 9:49:02 AM MCMIS snapshot date: 04/29/2022

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.